



Maxim Integrated

MAX6863UK225+T

Tau Wae:

MAX6863UK225+T

Kaihanga / Waitohu:

Maxim Integrated

Whakaahuatanga hua

IC MPU SUPERVISOR SOT23-5

Ngā Rauemi:

- 1.MAX6863UK225+T.pdf
- 2.MAX6863UK225+T.pdf

RoHs Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

17340 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o MAX6863UK225+T

TAU WAE	MAX6863UK225+T
KAIHANGA	Maxim Integrated
WHAKAAHUATANGA	IC MPU SUPERVISOR SOT23-5
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	17340 pcs
PEPA RARAUNGA	1.MAX6863UK225+T.pdf 2.MAX6863UK225+T.pdf
PUTANGA - TAE	2.235V
MOMO	Simple Reset/Power-On Reset
PŪRERE PŪRERE WHAKARATO	SOT-23-5
RAUPAPA	-
TAUTUHI TAUTUHI	Adjustable/Selectable
TAUTUHI ANŌ	Active Low
PACKAGING	Strip
PAA / CASE	SC-74A, SOT-753
WHAKAPUTA	Open Drain or Open Collector
ĒTAHI INGOA	MAX6863UK225+ MAX6863UK225+TCT MAX6863UK225+TCT-ND
TAE MAHI	-40°C ~ 85°C (TA)
TE MAHA O NGA TAUMAHA AROTURUKI	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Supervisor Open Drain or Open Collector 1 Channel SOT-23-5

Ngā tūtohu e hāngai ana

Maxim Integrated MAX6863UK225+T	MAX6863UK225+T Kaiwhiwhi	MAX6863UK225+T Kaiwhakarato
MAX6863UK225+T Utu	MAX6863UK225+T Pikitia	MAX6863UK225+T Whakaahua
MAX6863UK225+T PDF Datasheet	MAX6863UK225+T Download Datasheet	Tuhinga MAX6863UK225+T
MAX6863UK225+T Stock	Hokona MAX6863UK225+T	Hokona Maxim Integrated MAX6863UK225+T
Maxim Integrated MAX6863UK225+T	Maxim Integrated Kaiwhakarato	Maxim Integrated Kaiwhiwhi
Maxim Integrated MAX6863UK225+T		

Ngā Hua e hāngai ana

<p>MAX6862UK43+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 3125 pcs</p> <p>RFQ</p>	<p>MAX6863UK17+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 19713 pcs</p> <p>RFQ</p>
<p>MAX6863UK19+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 20205 pcs</p> <p>RFQ</p>	<p>MAX6863UK28+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 22473 pcs</p> <p>RFQ</p>
<p>MAX6863UK29+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 21230 pcs</p> <p>RFQ</p>	<p>MAX6863UK30+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 4383 pcs</p> <p>RFQ</p>
<p>MAX6863UK25+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 4263 pcs</p> <p>RFQ</p>	<p>MAX6863UK18+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 4904 pcs</p> <p>RFQ</p>
<p>MAX6863UK26+ Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 19626 pcs</p> <p>RFQ</p>	<p>MAX6863UK16+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 4747 pcs</p> <p>RFQ</p>
<p>MAX6862UK33+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 5962 pcs</p> <p>RFQ</p>	<p>MAX6863UK26+T Kaihanga: Maxim Integrated Whakaahuatanga: IC MPU SUPERVISOR SOT23-5 I roto i te taonga: 51561 pcs</p> <p>RFQ</p>

