




CPL-5220-16-TNC-79

| | |
|---------------------|---|
| Tau Wae: | CPL-5220-16-TNC-79 |
| Kaihanga / Waitohu: | Bel |
| Whakaahuatanga hua | RF DIR COUPLER 500MHZ-1GHZ |
| Ngā Rauemi: |  CPL-5220-16-TNC-79.pdf |
| RoHS Tūnga |  Kei roto nga rangatira / RoHS kaore i te ture |
| Waeheere Stock | 6310 pcs stock |
| Tuhinga mai i | Hong Kong |
| Te Ara Tuhi | DHL/Fedex/TNT/UPS/EMS |

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o CPL-5220-16-TNC-79

| | |
|---|--|
| TAU WAE | CPL-5220-16-TNC-79 |
| KAIHANGA | Bel |
| WHAKAAHUATANGA | RF DIR COUPLER 500MHZ-1GHZ |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Kei roto nga rangatira / RoHS kaore i te ture |
| HE RAHINGA KEI TE WĀTEA | 6310 pcs |
| PEPA RARAUNGA |  CPL-5220-16-TNC-79.pdf |
| PŪRERE PŪRERE WHAKARATO | - |
| RAUPAPA | - |
| HOKI HOKI | - |
| MANA - MAX | 50W |
| PACKAGING | Bulk |
| PAA / CASE | TNC In-Line Module |
| TAUMATA WHAKAARO MOE (MSL) | 1 (Unlimited) |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Contains lead / RoHS non-compliant |
| WHAKAMOTU | - |
| TE HAINATANGA WHAKATAUNGA | 0.4dB |
| RAUTANGA | 500MHz ~ 1GHz |
| WHAKAAHUATANGA TAIPITOPITO | RF Directional Coupler 500MHz ~ 1GHz 16dB ± 1dB 50W TNC In-Line Module |
| HONONGA TAE | 16dB ± 1dB |
| HE MOMO HOAHOA | Standard |
| NGA TONO | - |

Ngā tūtohu e hāngai ana

| | | |
|---|---|---|
| Bel CPL-5220-16-TNC-79 | CPL-5220-16-TNC-79 Kaiwhiwhi | CPL-5220-16-TNC-79 Kaiwhakarato |
| CPL-5220-16-TNC-79 Utu | CPL-5220-16-TNC-79 Pikitia | CPL-5220-16-TNC-79 Whakaahua |
| CPL-5220-16-TNC-79 PDF Datasheet | CPL-5220-16-TNC-79 Download Datasheet | Tuhinga CPL-5220-16-TNC-79 |
| CPL-5220-16-TNC-79 Stock | Hokona CPL-5220-16-TNC-79 | Hokona Bel CPL-5220-16-TNC-79 |
| Bel CPL-5220-16-TNC-79 | Bel Kaiwhakarato | Bel Kaiwhiwhi |
| Bel CPL-5220-16-TNC-79 | Cinch Connectivity Solutions CPL-5220-16-TNC-79 | Cinch Connectivity Solutions AIM-Cambridge CPL-5220-16-TNC-79 |
| Cinch Connectivity Solutions Johnson CPL-5220-16-TNC-79 | Cinch Connectivity Solutions Midwest Microwave CPL-5220-16-TNC-79 | Cinch Connectivity Solutions Semflex CPL-5220-16-TNC-79 |
| Cinch Connectivity Solutions Trompeter CPL-5220-16-TNC-79 | Cinch Connectivity Solutions Vitelec CPL-5220-16-TNC-79 | |

Ngā Hua e hāngai ana

| | |
|---|--|
|  <p>CPL-5220-06-TNC-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 3188 pcs</p> <p>RFQ</p> |  <p>CPL-5221-06-TNC-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 1GHZ-4GHZ I roto i te taonga: 5524 pcs</p> <p>RFQ</p> |
|  <p>CPL-5220-16-NNN-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 4124 pcs</p> <p>RFQ</p> |  <p>CPL-5220-20-TNC-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 4777 pcs</p> <p>RFQ</p> |
|  <p>CPL-5220-20-NNN-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 2775 pcs</p> <p>RFQ</p> |  <p>CPL-5221-06-NNN-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 1GHZ-4GHZ I roto i te taonga: 6248 pcs</p> <p>RFQ</p> |
|  <p>CPL-5221-06-SMA-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 1GHZ-4GHZ I roto i te taonga: 5718 pcs</p> <p>RFQ</p> |  <p>CPL-5220-10-SMA-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 158 pcs</p> <p>RFQ</p> |
|  <p>CPL-5220-10-NNN-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 5752 pcs</p> <p>RFQ</p> |  <p>CPL-5220-10-TNC-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 4137 pcs</p> <p>RFQ</p> |
|  <p>CPL-5220-16-SMA-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 2831 pcs</p> <p>RFQ</p> |  <p>CPL-5220-20-SMA-79 Kaihanga: Bel Whakaahuatanga: RF DIR COUPLER 500MHZ-1GHZ I roto i te taonga: 120 pcs</p> <p>RFQ</p> |