





AVX Corporation


CP0402A1890ALTR

Tau Wae:	CP0402A1890ALTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.88-1.9GHZ 0402
Ngā Rauemi:	 CP0402A1890ALTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waehe Stock	502970 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o CP0402A1890ALTR

TAU WAE	CP0402A1890ALTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.88-1.9GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	502970 pcs
PEPA RARAUNGA	 CP0402A1890ALTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	25dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-36dB
TE HAINATANGA WHAKATAUNGA	0.5dB
RAUTANGA	1.88GHz ~ 1.9GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler DECT 1.88GHz ~ 1.9GHz 12.3dB 3W 0402 (1005 Metric)
HONONGA TAE	12.3dB
HE MOMO HOAHOA	Standard
NGA TONO	DECT

Ngā tūtohu e hāngai ana

AVX Corporation CP0402A1890ALTR	CP0402A1890ALTR Kaiwhiwhi	CP0402A1890ALTR Kaiwhakarato
CP0402A1890ALTR Utu	CP0402A1890ALTR Pikitia	CP0402A1890ALTR Whakaahua
CP0402A1890ALTR PDF Datasheet	CP0402A1890ALTR Download Datasheet	Tuhinga CP0402A1890ALTR
CP0402A1890ALTR Stock	Hokona CP0402A1890ALTR	Hokona AVX Corporation CP0402A1890ALTR
AVX Corporation CP0402A1890ALTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaiwhiwhi
AVX Corporation CP0402A1890ALTR	AVX Corporation [MIL] CP0402A1890ALTR	

Ngā Hua e hāngai ana

 <p>CP0402A1880CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 432171 pcs</p> <p>RFQ</p>	 <p>CP0402A1880ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 415023 pcs</p> <p>RFQ</p>
 <p>CP0402A1880CNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 460616 pcs</p> <p>RFQ</p>	 <p>CP0402A1880ENTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 479821 pcs</p> <p>RFQ</p>
 <p>CP0402A1880DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 459126 pcs</p> <p>RFQ</p>	 <p>CP0402A1950CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 486772 pcs</p> <p>RFQ</p>
 <p>CP0402A1950ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 392608 pcs</p> <p>RFQ</p>	 <p>CP0402A1950BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 487993 pcs</p> <p>RFQ</p>
 <p>CP0402A1950ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 414676 pcs</p> <p>RFQ</p>	 <p>CP0402A1880DNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 435221 pcs</p> <p>RFQ</p>
 <p>CP0402A1950DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 474253 pcs</p> <p>RFQ</p>	 <p>CP0402A1890ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0402 I roto i te taonga: 459521 pcs</p> <p>RFQ</p>