



Leader Tech Inc.

### 59-CBSA-1.0X1.25X0.5

Tau Wae: 59-CBSA-1.0X1.25X0.5  
 Kaihanga / Waitohu: Leader Tech Inc.  
 Whakaahuatanga hua: 59 SERIES CBS SHIELD ASSEMBLY -  
 PDF 1.59-CBSA-1.0X1.25X0.5.pdf  
 PDF 2.59-CBSA-1.0X1.25X0.5.pdf  
 Ngā Rauemi: Whakahaerehia te kore utu / RoHS  
 RoHs Tūnga: Whakahaerehia te kore utu / RoHS  
 Waehe Stock: 5272 pcs stock  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o 59-CBSA-1.0X1.25X0.5

TAU WAE	59-CBSA-1.0X1.25X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	59 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	5272 pcs
PEPA RARAUNGA	1.59-CBSA-1.0X1.25X0.5.pdf 2.59-CBSA-1.0X1.25X0.5.pdf
WHĀNUI - WHĀNUI	1.000" (25.40mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	59-CBSA-1.0X1.25X0.4 59-CBSA-1.0X1.25X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	1.250" (31.75mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.000" (25.40mm) X 1.250" (31.75mm) Vent Holes in Pattern Through Hole

#### Ngā tūtohu e hāngai ana

Leader Tech Inc. 59-CBSA-1.0X1.25X0.5	59-CBSA-1.0X1.25X0.5 Kaiwhiwhi	59-CBSA-1.0X1.25X0.5 Kaiwhakarato
59-CBSA-1.0X1.25X0.5 Utu	59-CBSA-1.0X1.25X0.5 Pikitia	59-CBSA-1.0X1.25X0.5 Whakaahua
59-CBSA-1.0X1.25X0.5 PDF Datasheet	59-CBSA-1.0X1.25X0.5 Download Datasheet	Tuhinga 59-CBSA-1.0X1.25X0.5
59-CBSA-1.0X1.25X0.5 Stock	Hokona 59-CBSA-1.0X1.25X0.5	Hokona Leader Tech Inc. 59-CBSA-1.0X1.25X0.5
Leader Tech Inc. 59-CBSA-1.0X1.25X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 59-CBSA-1.0X1.25X0.5		

#### Ngā Hua e hāngai ana

<p><b>59-CBSA-1.0X1.75X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 4770 pcs</p> <p><b>RFQ</b></p>	<p><b>59-CBSA-1.0X1.5X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59-CBSA-1.0X1.5X0.5--59S45--CIRC                  I roto i te taonga: 8186 pcs</p> <p><b>RFQ</b></p>
<p><b>59-CBSA-0.75X5.0X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 4252 pcs</p> <p><b>RFQ</b></p>	<p><b>59-CBSA-0.75X6.0X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 4422 pcs</p> <p><b>RFQ</b></p>
<p><b>59-CBSA-0.75X5.25X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 3619 pcs</p> <p><b>RFQ</b></p>	<p><b>59-CBSA-1.0X2.0X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 5170 pcs</p> <p><b>RFQ</b></p>
<p><b>59-CBSA-0.75X5.5X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 3435 pcs</p> <p><b>RFQ</b></p>	<p><b>59-CBSA-1.0X1.0X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 6305 pcs</p> <p><b>RFQ</b></p>
<p><b>59-CBSA-1.0X2.5X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 4550 pcs</p> <p><b>RFQ</b></p>	<p><b>59-CBSA-0.75X5.75X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 4365 pcs</p> <p><b>RFQ</b></p>
<p><b>59-CBSA-1.0X1.5X0.4</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 5649 pcs</p> <p><b>RFQ</b></p>	<p><b>59-CBSA-1.0X2.25X0.5</b>                  Kaihanga: Leader Tech Inc.                  Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY -                  I roto i te taonga: 4732 pcs</p> <p><b>RFQ</b></p>