





AVX Corporation


CP0402A1960ALTR

Tau Wae:	CP0402A1960ALTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.93-1.99GHZ 0402
Ngā Rauemi:	 CP0402A1960ALTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	433792 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o CP0402A1960ALTR

TAU WAE	CP0402A1960ALTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.93-1.99GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	433792 pcs
PEPA RARAUNGA	 CP0402A1960ALTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	25dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-35dB
TE HAINATANGA WHAKATAUNGA	0.5dB
RAUTANGA	1.93GHz ~ 1.99GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler PCS 1.93GHz ~ 1.99GHz 12dB 3W 0402 (1005 Metric)
HONONGA TAE	12dB
HE MOMO HOAHOA	Standard
NGA TONO	PCS

Ngā tūtohu e hāngai ana

AVX Corporation CP0402A1960ALTR	CP0402A1960ALTR Kaihiwhi	CP0402A1960ALTR Kaiwhakarato
CP0402A1960ALTR Utu	CP0402A1960ALTR Pikitia	CP0402A1960ALTR Whakaahua
CP0402A1960ALTR PDF Datasheet	CP0402A1960ALTR Download Datasheet	Tuhinga CP0402A1960ALTR
CP0402A1960ALTR Stock	Hokona CP0402A1960ALTR	Hokona AVX Corporation CP0402A1960ALTR
AVX Corporation CP0402A1960ALTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0402A1960ALTR	AVX Corporation [MIL] CP0402A1960ALTR	

Ngā Hua e hāngai ana

 <p>CP0402A1950BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 487993 pcs</p> <p>RFQ</p>	 <p>CP0402A1950CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 486772 pcs</p> <p>RFQ</p>
 <p>CP0402A1950DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 474253 pcs</p> <p>RFQ</p>	 <p>CP0402A2350FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.35GHZ 0402 I roto i te taonga: 489817 pcs</p> <p>RFQ</p>
 <p>CP0402A1960DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 508557 pcs</p> <p>RFQ</p>	 <p>CP0402A1950FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 464652 pcs</p> <p>RFQ</p>
 <p>CP0402A2400ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4GHZ 0402 I roto i te taonga: 513383 pcs</p> <p>RFQ</p>	 <p>CP0402A1960CNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 380691 pcs</p> <p>RFQ</p>
 <p>CP0402A1950ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 414676 pcs</p> <p>RFQ</p>	 <p>CP0402A2140ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.14GHZ 0402 I roto i te taonga: 383642 pcs</p> <p>RFQ</p>
 <p>CP0402A1950ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 392608 pcs</p> <p>RFQ</p>	 <p>CP0402A1960ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 454403 pcs</p> <p>RFQ</p>