



H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S

Tau Wae:	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S
Kaihanga / Waitohu:	BEI Sensors
Whakaahuatanga hua	ROTARY ENCODR INCREMENTAL 100PPR
Ngā Rauemi:	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S.pdf
Waehere Stock	150 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S

TAU WAE	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S
KAIHANGA	BEI Sensors
WHAKAAHUATANGA	ROTARY ENCODR INCREMENTAL 100PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	150 pcs
PEPA RARAUNGA	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S.pdf
TUHINGA O MUA	-
KĀHUA WHAKAMUTUNGA	Connector
RAUPAPA	H20
KO TE ROTATIONAL LIFE (CYCLES MIN)	1.5B
PULSES IA REVOLUTION	100
MOMO PUTANGA	Quadrature (Incremental)
ĒTAHI INGOA	01046-090
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Shaft

Ngā tūtohu e hāngai ana

BEI Sensors H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Kaiwhiwhi	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Kaiwhakarato
H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Utu	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Pikitia	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Whakaahua
H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S PDF Datasheet	H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Download Datasheet	Tuhinga H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S
H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S Stock	Hokona H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S	Hokona BEI Sensors H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S
BEI Sensors H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S	BEI Sensors Kaiwhakarato	BEI Sensors Kaiwhiwhi
BEI Sensors H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S	Sensata Technologies – BEI Sensors H20DB-37-F28-SS-100-AC-5V/V-SM16-EX-S	

Ngā Hua e hāngai ana

<p>H20DA-37-50-A-24V/OC-SCS132 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODER INCREMENTAL 50PPR I roto i te taonga: 227 pcs</p> <p>RFQ</p>	<p>H20DB-25-SS-500-ABZ-15V/OCR-SCS18-S Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 500PPR I roto i te taonga: 216 pcs</p> <p>RFQ</p>
<p>H20DB-37-F5-SS-500-ABZC-28V/V-SM18-S Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 500PPR I roto i te taonga: 165 pcs</p> <p>RFQ</p>	<p>H20DB-37-F5-SS-100-AB-24V/OCR-SM14 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 100PPR I roto i te taonga: 219 pcs</p> <p>RFQ</p>
<p>H20DA-37-600-AB-15V/OC-SM14 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 600PPR I roto i te taonga: 171 pcs</p> <p>RFQ</p>	<p>H20DB-37-F5-SS-500-AB-5V/V-SM16-EX-S Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 500PPR I roto i te taonga: 109 pcs</p> <p>RFQ</p>
<p>H20DB-25-SS-2000-T2-AB-28V/V-SM16-S Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODER INCREMENTAL 2PPR I roto i te taonga: 249 pcs</p> <p>RFQ</p>	<p>H20DB-37-F5-SS-336-AB-24V/OCR-SM14 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 336PPR I roto i te taonga: 217 pcs</p> <p>RFQ</p>
<p>H20DB-25-SS-100-AC-28V/V-SK8 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 100PPR I roto i te taonga: 195 pcs</p> <p>RFQ</p>	<p>H20DB-37-F5-SS-500-ABZC-28V/V-SM18 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 500PPR I roto i te taonga: 253 pcs</p> <p>RFQ</p>
<p>H20DB-37-F5-SS-500-ABC-28V/5-SM16-S Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODR INCREMENTAL 500PPR I roto i te taonga: 192 pcs</p> <p>RFQ</p>	<p>H20DB-25-SS-5-AB-24V/OCR-SCS24 Kaihanga: BEI Sensors Whakaahuatanga: ROTARY ENCODER INCREMENTAL 5PPR I roto i te taonga: 247 pcs</p> <p>RFQ</p>