



49L-CBSA-4.0X5.75X0.4

Tau Wae:	49L-CBSA-4.0X5.75X0.4
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	49L SERIES CBS SHIELD ASSEMBLY
Ngā Rauemi:	49L-CBSA-4.0X5.75X0.4.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3193 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 49L-CBSA-4.0X5.75X0.4

TAU WAE	49L-CBSA-4.0X5.75X0.4
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	49L SERIES CBS SHIELD ASSEMBLY
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3193 pcs
PEPA RARAUNGA	49L-CBSA-4.0X5.75X0.4.pdf
WHĀNUI - WHĀNUI	4.000" (101.60mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	40-CBS
PACKAGING	Bulk
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	5.750" (146.05mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.400" (10.16mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 4.000" (101.60mm) X 5.750" (146.05mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 49L-CBSA-4.0X5.75X0.4	49L-CBSA-4.0X5.75X0.4 Kaiwhiwhi	49L-CBSA-4.0X5.75X0.4 Kaiwhakarato
49L-CBSA-4.0X5.75X0.4 Utu	49L-CBSA-4.0X5.75X0.4 Pikitia	49L-CBSA-4.0X5.75X0.4 Whakaahua
49L-CBSA-4.0X5.75X0.4 PDF Datasheet	49L-CBSA-4.0X5.75X0.4 Download Datasheet	Tuhinga 49L-CBSA-4.0X5.75X0.4
49L-CBSA-4.0X5.75X0.4 Stock	Hokona 49L-CBSA-4.0X5.75X0.4	Hokona Leader Tech Inc. 49L-CBSA-4.0X5.75X0.4
Leader Tech Inc. 49L-CBSA-4.0X5.75X0.4	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 49L-CBSA-4.0X5.75X0.4		

Ngā Hua e hāngai ana

<p>49L-CBSA-4.0X4.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3625 pcs</p> <p>RFQ</p>	<p>49L-CBSA-4.0X4.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3074 pcs</p> <p>RFQ</p>
<p>49L-CBSA-4.0X5.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3165 pcs</p> <p>RFQ</p>	<p>49L-CBSA-4.25X5.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3260 pcs</p> <p>RFQ</p>
<p>49L-CBSA-4.25X5.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3055 pcs</p> <p>RFQ</p>	<p>49L-CBSA-4.25X4.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3293 pcs</p> <p>RFQ</p>
<p>49L-CBSA-4.25X4.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3673 pcs</p> <p>RFQ</p>	<p>49L-CBSA-4.0X4.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3782 pcs</p> <p>RFQ</p>
<p>49L-CBSA-4.25X4.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3231 pcs</p> <p>RFQ</p>	<p>49L-CBSA-4.0X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3281 pcs</p> <p>RFQ</p>
<p>49L-CBSA-4.0X5.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3552 pcs</p> <p>RFQ</p>	<p>49L-CBSA-4.0X5.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49L SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3729 pcs</p> <p>RFQ</p>