




## 2450BL14B100

Tau Wae:	2450BL14B100
Kaihanga / Waitohu:	Johanson Technology
Whakaahuatanga hua	BALUN 2.4GHZ-2.5GHZ 50/100 0603
Ngā Rauemi:	 <a href="#">2450BL14B100.pdf</a>
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waeheere Stock	6408 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













## Ngā whakaaturanga o 2450BL14B100

TAU WAE	2450BL14B100
KAIHANGA	Johanson Technology
WHAKAAHUATANGA	BALUN 2.4GHZ-2.5GHZ 50/100 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	6408 pcs
PEPA RARAUNGA	 <a href="#">2450BL14B100.pdf</a>
RAUPAPA	2450
HOKI HOKI (MIN)	9.5dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Bulk
PAA / CASE	0603 (1608 Metric)
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.3dB
HAAPAHA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	2.4GHz ~ 2.5GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 2.4GHz ~ 2.5GHz 50 / 100 Ohm 0603 (1608 Metric)

## Ngā tūtohu e hāngai ana

Johanson Technology 2450BL14B100	2450BL14B100 Kaiwhiwhi	2450BL14B100 Kaiwhakarato
2450BL14B100 Utu	2450BL14B100 Pikitia	2450BL14B100 Whakaahua
2450BL14B100 PDF Datasheet	2450BL14B100 Download Datasheet	Tuhinga 2450BL14B100
2450BL14B100 Stock	Hokona 2450BL14B100	Hokona Johanson Technology 2450BL14B100
Johanson Technology 2450BL14B100	Johanson Technology Kaiwhakarato	Johanson Technology Kaiwhiwhi
Johanson Technology 2450BL14B100	Johanson 2450BL14B100	Johanson Technology Inc. 2450BL14B100

## Ngā Hua e hāngai ana

 <p><b>2450BL07A0100T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0402 I roto i te taonga: 6085 pcs</p> <p><b>RFQ</b></p>	 <p><b>2450BL15B100E</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0805 I roto i te taonga: 282519 pcs</p> <p><b>RFQ</b></p>
 <p><b>2450BL14B200T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/200 0603 I roto i te taonga: 4504 pcs</p> <p><b>RFQ</b></p>	 <p><b>2450BL07A0050T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0402 I roto i te taonga: 3869 pcs</p> <p><b>RFQ</b></p>
 <p><b>2450BL15B050E</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0805 I roto i te taonga: 294392 pcs</p> <p><b>RFQ</b></p>	 <p><b>2450BL14C200T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/200 0603 I roto i te taonga: 496504 pcs</p> <p><b>RFQ</b></p>
 <p><b>2450AT45A100E</b> Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 2.4GHZ CHIP SOLDER SMD I roto i te taonga: 194676 pcs</p> <p><b>RFQ</b></p>	 <p><b>2450AT44A100E</b> Kaihanga: Johanson Technology Whakaahuatanga: RF ANT 2.4GHZ CHIP SOLDER SMD I roto i te taonga: 3720 pcs</p> <p><b>RFQ</b></p>
 <p><b>2450BL14B100T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 2801 pcs</p> <p><b>RFQ</b></p>	 <p><b>2450BL05A0100T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.3GHZ-2.69GHZ 50/100 0202 I roto i te taonga: 346165 pcs</p> <p><b>RFQ</b></p>
 <p><b>2450BL14B050T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 2880 pcs</p> <p><b>RFQ</b></p>	 <p><b>2450BL14C050T</b> Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 148312 pcs</p> <p><b>RFQ</b></p>