



Leader Tech Inc.



LEADER
TECH
a HEICO company


59-CBSFDSV-3.75X4.25X0.5

Tau Wae:	59-CBSFDSV-3.75X4.25X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	59-CBSFDSV-3.75X4.25X0.50--59S15
Ngā Rauemi:	 59-CBSFDSV-3.75X4.25X0.5.pdf
Waehere Stock	3001 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o 59-CBSFDSV-3.75X4.25X0.5

TAU WAE	59-CBSFDSV-3.75X4.25X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	59-CBSFDSV-3.75X4.25X0.50--59S15
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	3001 pcs
PEPA RARAUNGA	 59-CBSFDSV-3.75X4.25X0.5.pdf
WHĀNUI - WHĀNUI	3.750" (95.25mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
ĒTAHI INGOA	59-CBSFDSV-3.75X4.25X0.50 59-CBSFDSV-3.75X4.25X0.50-ND
MOMO TAE	Through Hole
TE ROA - WHĀNUI	4.250" (107.95mm)
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 3.750" (95.25mm) X 4.250" (107.95mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 59-CBSFDSV-3.75X4.25X0.5	59-CBSFDSV-3.75X4.25X0.5 Kaiwhiwhi	59-CBSFDSV-3.75X4.25X0.5 Kaiwhakarato
59-CBSFDSV-3.75X4.25X0.5 Utu	59-CBSFDSV-3.75X4.25X0.5 Pikitia	59-CBSFDSV-3.75X4.25X0.5 Whakaahua
59-CBSFDSV-3.75X4.25X0.5 PDF Datasheet	59-CBSFDSV-3.75X4.25X0.5 Download Datasheet	Tuhinga 59-CBSFDSV-3.75X4.25X0.5
59-CBSFDSV-3.75X4.25X0.5 Stock	Hokona 59-CBSFDSV-3.75X4.25X0.5	Hokona Leader Tech Inc. 59-CBSFDSV-3.75X4.25X0.5
Leader Tech Inc. 59-CBSFDSV-3.75X4.25X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 59-CBSFDSV-3.75X4.25X0.5		

Ngā Hua e hāngai ana

 <p>59-CBSFN-1.0X1.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSFN-1.0X1.75X0.5--59S160--C I roto i te taonga: 3616 pcs</p> <p>RFQ</p>	 <p>59-CBSF-1.25X2.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSF-1.25X2.25X0.5--59S138--C I roto i te taonga: 5636 pcs</p> <p>RFQ</p>
 <p>59-CBSASV-1.5X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSASV-1.5X3.75X0.5--59S157-- I roto i te taonga: 3650 pcs</p> <p>RFQ</p>	 <p>59-CBSF-2.0X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSF-2.0X3.5X0.50--59S134--CI I roto i te taonga: 4034 pcs</p> <p>RFQ</p>
 <p>59-CBSFNSV-1.5X1.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSFNSV-1.5X1.5X0.5--59S155-- I roto i te taonga: 3635 pcs</p> <p>RFQ</p>	 <p>59-CBSAP-2.25X2.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSAP-2.25X2.25X0.5--59S139-- I roto i te taonga: 3742 pcs</p> <p>RFQ</p>
 <p>59-CBSFNSV-2.25X2.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSFNSV-2.25X2.5X0.50--59S154 I roto i te taonga: 4598 pcs</p> <p>RFQ</p>	 <p>59-CBSFP-2.0X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSFP-2.0X4.0X0.5--59S152--CI I roto i te taonga: 3775 pcs</p> <p>RFQ</p>
 <p>59-CBSFNSV-1.75X4.0X0.8 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSFNSV-1.75X4.0X0.8--59S159- I roto i te taonga: 3064 pcs</p> <p>RFQ</p>	 <p>59-CBSF-1.0X2.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSF-1.0X2.25X0.50--59S87--CI I roto i te taonga: 6727 pcs</p> <p>RFQ</p>
 <p>59-CBSFP-1.0X1.75 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSFP-1.0X1.75--59S48--CIRCUI I roto i te taonga: 16868 pcs</p> <p>RFQ</p>	 <p>59-CBSF-2.0X2.0X1.0 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59-CBSF-2.0X2.0X1.0--59S153--CIR I roto i te taonga: 10955 pcs</p> <p>RFQ</p>

Copyright © 2020 Kaitoha Kaitoha o nga waahanga hiko

Ī-mēra: Info@infinity-electronic.com

Wāhi noho: 17F, Gaylord Hangarau Hokohoko, 114-118 Lockhart Road, Wan Chai, Hong Kong

