

BOURNS®

Bourns, Inc.

3315C-102-006L

Tau Wae:

3315C-102-006L

Kaihanga / Waitohu:

Bourns, Inc.

Whakaahuatanga hua

ROTARY ENCODER MECHANICAL 6PPR

Ngā Rauemi:

3315C-102-006L.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

23549 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 3315C-102-006L

TAU WAE	3315C-102-006L
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	ROTARY ENCODER MECHANICAL 6PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	23549 pcs
PEPA RARAUNGA	3315C-102-006L.pdf
TUHINGA O MUA	-
KĀHUA WHAKAMUTUNGA	PC Pin
RAUPAPA	3315
KO TE ROTATIONAL LIFE (CYCLES MIN)	25K
PULSES IA REVOLUTION	6
MOMO PUTANGA	Quadrature (Incremental)
WHAKATAKOTORANGA	Right Angle
MOMO TAE	Panel, PCB Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MOMO KUPUTUHI	Mechanical
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	1/8" Dia Flatted End

Ngā tūtohu e hāngai ana

Bourns, Inc. 3315C-102-006L	3315C-102-006L Kaiwhiwhi	3315C-102-006L Kaiwhakarato
3315C-102-006L Utu	3315C-102-006L Pikitia	3315C-102-006L Whakaahua
3315C-102-006L PDF Datasheet	3315C-102-006L Download Datasheet	Tuhinga 3315C-102-006L
3315C-102-006L Stock	Hokona 3315C-102-006L	Hokona Bourns, Inc. 3315C-102-006L
Bourns, Inc. 3315C-102-006L	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. 3315C-102-006L	Bourns Inc. 3315C-102-006L	J.W. Miller / Bourns 3315C-102-006L

Ngā Hua e hāngai ana

<p>3315C-001-006L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 21411 pcs</p> <p>RFQ</p>	<p>3315C-002-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 32531 pcs</p> <p>RFQ</p>
<p>33156 Kaihanga: Agastat Relays / TE Connectivity Whakaahuatanga: CONN SPADE TERM 14-16AWG #8 BLU I roto i te taonga: 4699 pcs</p> <p>RFQ</p>	<p>3315P-001-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 46063 pcs</p> <p>RFQ</p>
<p>3315C-101-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 29809 pcs</p> <p>RFQ</p>	<p>3315C-111-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 26735 pcs</p> <p>RFQ</p>
<p>3315P-025-006L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 27027 pcs</p> <p>RFQ</p>	<p>3315P-001-006L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 33187 pcs</p> <p>RFQ</p>
<p>3315C-001-006 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 3848 pcs</p> <p>RFQ</p>	<p>3315C-125-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 4256 pcs</p> <p>RFQ</p>
<p>3315C-001-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 27335 pcs</p> <p>RFQ</p>	<p>3315C-102-016L Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 22726 pcs</p> <p>RFQ</p>