



TDK Corporation

### DPX165900DT-8025A1

Tau Wae: DPX165900DT-8025A1  
 Kaihanga / Waitohu: TDK Corporation  
 Whakaahuatanga hua: RF DIPLEXER 2.45GHZ/5.5GHZ 0805  
 Ngā Rauemi: DPX165900DT-8025A1.pdf  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Waeheere Stock: 123796 pcs stock  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o DPX165900DT-8025A1

TAU WAE	DPX165900DT-8025A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	RF DIPLEXER 2.45GHZ/5.5GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	123796 pcs
PEPA RARAUNGA	DPX165900DT-8025A1.pdf
RAUPAPA	DPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	22dB / 12dB
PACKAGING	Original-Reel®
PAA / CASE	0805 (2012 Metric), 6 PC Pad
ĒTAHI INGOA	445-15671-6
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	18.00dB / 26.00dB
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	23.00dB / 31.00dB
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	2.4GHz ~ 2.5GHz / 5.1GHz ~ 5.9GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 2.4GHz ~ 2.5GHz / 5.1GHz ~ 5.9GHz 0805 (2012 Metric), 6 PC Pad

#### Ngā tūtohu e hāngai ana

TDK Corporation DPX165900DT-8025A1	DPX165900DT-8025A1 Kaiwhiwhi	DPX165900DT-8025A1 Kaiwhakarato
DPX165900DT-8025A1 Utu	DPX165900DT-8025A1 Pikitia	DPX165900DT-8025A1 Whakaahua
DPX165900DT-8025A1 PDF Datasheet	DPX165900DT-8025A1 Download Datasheet	Tuhinga DPX165900DT-8025A1
DPX165900DT-8025A1 Stock	Hokona DPX165900DT-8025A1	Hokona TDK Corporation DPX165900DT-8025A1
TDK Corporation DPX165900DT-8025A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation DPX165900DT-8025A1		

#### Ngā Hua e hāngai ana

<p><b>DPX165850DT-8040A3</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD                  I roto i te taonga: 240643 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8030D1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 1740.5MZH/5.425GHZ 0603                  I roto i te taonga: 350649 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165900DT-8125A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.5GHZ 0603                  I roto i te taonga: 93010 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8026A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603                  I roto i te taonga: 350662 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165950DT-8026D1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603                  I roto i te taonga: 283906 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165850DT-8032A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 0603 4 PC PAD                  I roto i te taonga: 290871 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165850DT-8033B1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD                  I roto i te taonga: 56870 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8018A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603                  I roto i te taonga: 113685 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165850DT-8017A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.51GHZ 0603                  I roto i te taonga: 349299 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165850DT-8117A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 892MHZ/1.94GHZ 0603                  I roto i te taonga: 327478 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165850DT-8132A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 0603 4 PC PAD                  I roto i te taonga: 103713 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8030A1</b>                  Kaihanga: TDK Corporation                  Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603                  I roto i te taonga: 114140 pcs</p> <p><b>RFQ</b></p>

