



XMOS

XE232-1024-FB374-C40

Tau Wae:	XE232-1024-FB374-C40
Kaihanga / Waitohu:	XMOS
Whakaahuatanga hua	IC MCU 32BIT ROMLESS 374FBGA
Ngā Rauemi:	XE232-1024-FB374-C40.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3412 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o XE232-1024-FB374-C40

TAU WAE	XE232-1024-FB374-C40
KAIHANGA	XMOS
WHAKAAHUATANGA	IC MCU 32BIT ROMLESS 374FBGA
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3412 pcs
PEPA RARAUNGA	XE232-1024-FB374-C40.pdf
NGAOHIHI - WHAKAAETANGA (VCC / VDD)	0.95 V ~ 3.6 V
PŪRERE PŪRERE WHAKARATO	374-FBGA (18x18)
TERE	4000MIPS
RAUPAPA	XE
RAHI RAM	1M x 8
MOMO MOMO RATONGA	ROMless
RAHI MOTU RATONGA	-
NGA PAPA HANGA REO	-
PACKAGING	Tray
PAA / CASE	374-LFBGA
ĒTAHI INGOA	880-1105
OSCILLATOR MOMO	External
TAE MAHI	0°C ~ 70°C (TA)
TAU O I / O	176
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAE EEPROM	-
WHAKAAHUATANGA TAIPITOPITO	XCore XE Microcontroller IC 32-Bit 32-Core 4000MIPS ROMless 374-FBGA (18x18)
RARAUNGA RARAUNGA	-
NUI RAHI	32-Bit 32-Core
TE TUKATUKA CORE	XCore
HONONGA	RGMII, USB

Ngā tūtohu e hāngai ana

XMOS XE232-1024-FB374-C40	XE232-1024-FB374-C40 Kaiwhiwhi	XE232-1024-FB374-C40 Kaiwhakarato
XE232-1024-FB374-C40 Utu	XE232-1024-FB374-C40 Pikitia	XE232-1024-FB374-C40 Whakaahua
XE232-1024-FB374-C40 PDF Datasheet	XE232-1024-FB374-C40 Download Datasheet	Tuhinga XE232-1024-FB374-C40
XE232-1024-FB374-C40 Stock	Hokona XE232-1024-FB374-C40	Hokona XMOS XE232-1024-FB374-C40
XMOS XE232-1024-FB374-C40	XMOS Kaiwhakarato	XMOS Kaiwhiwhi
XMOS XE232-1024-FB374-C40		

Ngā Hua e hāngai ana

<p>XE232-1024-FB374-I40 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 374FBGA I roto i te taonga: 3249 pcs</p> <p>RFQ</p>	<p>XE216-512-FB236-C20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 236FBGA I roto i te taonga: 5097 pcs</p> <p>RFQ</p>
<p>XE216-256-FB236-I20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 236FBGA I roto i te taonga: 9011 pcs</p> <p>RFQ</p>	<p>XE2405 Kaihanga: JKL Components Corporation Whakaahuatanga: LAMP XENON RT-7 BI-PIN 24V I roto i te taonga: 51570 pcs</p> <p>RFQ</p>
<p>XE216-512-TQ128-C20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 128TQFP I roto i te taonga: 6459 pcs</p> <p>RFQ</p>	<p>XE216-512-FB236-I20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 236FBGA I roto i te taonga: 6042 pcs</p> <p>RFQ</p>
<p>XE216-256-TQ128-C20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 128TQFP I roto i te taonga: 6305 pcs</p> <p>RFQ</p>	<p>XE216-512-TQ128-I20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 128TQFP I roto i te taonga: 4600 pcs</p> <p>RFQ</p>
<p>XE216-256-TQ128-I20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 128TQFP I roto i te taonga: 6636 pcs</p> <p>RFQ</p>	<p>XE2410 Kaihanga: JKL Components Corporation Whakaahuatanga: LAMP XENON RT-7 BI-PIN 24V I roto i te taonga: 53598 pcs</p> <p>RFQ</p>
<p>XE216-256-FB236-C20 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 236FBGA I roto i te taonga: 5464 pcs</p> <p>RFQ</p>	<p>XE232-512-FB374-C40 Kaihanga: XMOS Whakaahuatanga: IC MCU 32BIT ROMLESS 374FBGA I roto i te taonga: 3504 pcs</p> <p>RFQ</p>