



TDK Corporation

HHM1564A4

Tau Wae:

HHM1564A4

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 824MHZ-894MHZ 50/200 0805

Ngā Rauemi:

HHM1564A4.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

432133 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HHM1564A4

TAU WAE	HHM1564A4
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 824MHZ-894MHZ 50/200 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	432133 pcs
PEPA RARAUNGA	HHM1564A4.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	10dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
ĒTAHI INGOA	445-3993-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.0dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 200 Ohm
MAHINGA RAWE	824MHz ~ 894MHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 824MHz ~ 894MHz 50 / 200 Ohm 0805 (2012 Metric)

Ngā tūtohu e hāngai ana

TDK Corporation HHM1564A4	HHM1564A4 Kaiwhiwhi	HHM1564A4 Kaiwhakarato
HHM1564A4 Utu	HHM1564A4 Pikitia	HHM1564A4 Whakaahua
HHM1564A4 PDF Datasheet	HHM1564A4 Download Datasheet	Tuhinga HHM1564A4
HHM1564A4 Stock	Hokona HHM1564A4	Hokona TDK Corporation HHM1564A4
TDK Corporation HHM1564A4	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM1564A4		

Ngā Hua e hāngai ana

<p>HHM1548E1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.2GHZ-3.9GHZ 50/200 0805 I roto i te taonga: 209833 pcs</p> <p>RFQ</p>	<p>HHM1589E1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/200 0805 I roto i te taonga: 435579 pcs</p> <p>RFQ</p>
<p>HHM1526 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.99GHZ 50/100 0805 I roto i te taonga: 69461 pcs</p> <p>RFQ</p>	<p>HHM1562B Kaihanga: TDK Corporation Whakaahuatanga: BALUN 5.15-5.875GHZ 50/100 0805 I roto i te taonga: 669816 pcs</p> <p>RFQ</p>
<p>HHM1525 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71GHZ-1.99GHZ 50/50 0805 I roto i te taonga: 532768 pcs</p> <p>RFQ</p>	<p>HHM1541E1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.5GHZ 50/75 0805 I roto i te taonga: 548409 pcs</p> <p>RFQ</p>
<p>HHM1591D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/100 0805 I roto i te taonga: 466597 pcs</p> <p>RFQ</p>	<p>HHM1583B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: 404898 pcs</p> <p>RFQ</p>
<p>HHM1589B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 470MHZ-710MHZ 6SMD I roto i te taonga: 234016 pcs</p> <p>RFQ</p>	<p>HHM1595A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3GHZ-8GHZ 50/100 0805 I roto i te taonga: 163352 pcs</p> <p>RFQ</p>
<p>HHM1534 Kaihanga: TDK Corporation Whakaahuatanga: BALUN DUAL 50/200 0805 I roto i te taonga: 205642 pcs</p> <p>RFQ</p>	<p>HHM1570B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0805 I roto i te taonga: 162835 pcs</p> <p>RFQ</p>