



Micrel / Microchip Technology

## SY10E111JC

Tau Wae:

SY10E111JC

Kaihanga / Waitohu:

Micrel / Microchip Technology

Whakaahuatanga hua

IC CLK BUFFER 1:9 28PLCC

Ngā Rauemi:

 SY10E111JC.pdf

RoHS Tūnga

 Kei roto nga rangatira / RoHS kaore i te ture

Waehe Stock

16675 pcs stock

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













## Ngā whakaaturanga o SY10E111JC

TAU WAE	SY10E111JC
KAIHANGA	Micrel / Microchip Technology
WHAKAAHUATANGA	IC CLK BUFFER 1:9 28PLCC
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	16675 pcs
PEPA RARAUNGA	 SY10E111JC.pdf
TUHINGA O MUA	4.2 V ~ 5.5 V
MOMO	Fanout Buffer (Distribution)
PŪRERE PŪRERE WHAKARATO	28-PLCC (11.51x11.51)
RAUPAPA	100E, ECLinPS™
RATONGA - WHAKAURU: WHAKAPUTA	1:9
PACKAGING	Tube
PAA / CASE	28-LCC (J-Lead)
WHAKAPUTA	PECL
TAE MAHI	0°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAURU	PECL
MOTUHAKA - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution) IC 1:9 28-LCC (J-Lead)
TAU WAE TUAKIRI	SY10E111

## Ngā tūtohu e hāngai ana

Micrel / Microchip Technology SY10E111JC	SY10E111JC Kaiwhiwhi	SY10E111JC Kaiwhakarato
SY10E111JC Utu	SY10E111JC Pikitia	SY10E111JC Whakaahua
SY10E111JC PDF Datasheet	SY10E111JC Download Datasheet	Tuhinga SY10E111JC
SY10E111JC Stock	Hokona SY10E111JC	Hokona Micrel / Microchip Technology SY10E111JC
Micrel / Microchip Technology SY10E111JC	Micrel / Microchip Technology Kaiwhakarato	Micrel / Microchip Technology Kaiwhiwhi
Micrel / Microchip Technology SY10E111JC	Microchip Technology SY10E111JC	Roving Networks / Microchip Technology SY10E111JC

## Ngā Hua e hāngai ana

 <p><b>SY10E111JI</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 16854 pcs</p> <p><b>RFQ</b></p>	 <p><b>SY10E111AJY-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 27490 pcs</p> <p><b>RFQ</b></p>
 <p><b>SY10E111JC-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 21840 pcs</p> <p><b>RFQ</b></p>	 <p><b>SY10E111AJC</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 20723 pcs</p> <p><b>RFQ</b></p>
 <p><b>SY10E111AJY</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 6593 pcs</p> <p><b>RFQ</b></p>	 <p><b>SY10E111AJC-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 24993 pcs</p> <p><b>RFQ</b></p>
 <p><b>SY10E111JY-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 4383 pcs</p> <p><b>RFQ</b></p>	 <p><b>SY10E111AEJY</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 28350 pcs</p> <p><b>RFQ</b></p>
 <p><b>SY10E111LEJC</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 18125 pcs</p> <p><b>RFQ</b></p>	 <p><b>SY10E111AEJY-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 6613 pcs</p> <p><b>RFQ</b></p>
 <p><b>SY10E111JY</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 18848 pcs</p> <p><b>RFQ</b></p>	 <p><b>SY10E111JI-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:9 28PLCC I roto i te taonga: 19964 pcs</p> <p><b>RFQ</b></p>