



AVX Corporation

CP0402A1960CNTR

Tau Wae:

CP0402A1960CNTR

Kaihanga / Waitohu:

AVX Corporation

Whakaahuatanga hua

RF DIR COUPLER 1.93-1.99GHZ 0402

Ngā Rauemi:

CP0402A1960CNTR.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

380691 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CP0402A1960CNTR

TAU WAE	CP0402A1960CNTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.93-1.99GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	380691 pcs
PEPA RARAUNGA	CP0402A1960CNTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	0.25dB
RAUTANGA	1.93GHz ~ 1.99GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 1.93GHz ~ 1.99GHz 3W 0402 (1005 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

Ngā tūtohu e hāngai ana

AVX Corporation CP0402A1960CNTR	CP0402A1960CNTR Kaihiwhi	CP0402A1960CNTR Kaiwhakarato
CP0402A1960CNTR Utu	CP0402A1960CNTR Pikitia	CP0402A1960CNTR Whakaahua
CP0402A1960CNTR PDF Datasheet	CP0402A1960CNTR Download Datasheet	Tuhinga CP0402A1960CNTR
CP0402A1960CNTR Stock	Hokona CP0402A1960CNTR	Hokona AVX Corporation CP0402A1960CNTR
AVX Corporation CP0402A1960CNTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0402A1960CNTR	AVX Corporation [MIL] CP0402A1960CNTR	

Ngā Hua e hāngai ana

<p>CP0402A1950FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 464652 pcs</p> <p>RFQ</p>	<p>CP0402A2350FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.35GHZ 0402 I roto i te taonga: 489817 pcs</p> <p>RFQ</p>
<p>CP0402A1960ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 433792 pcs</p> <p>RFQ</p>	<p>CP0402A1950CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 486772 pcs</p> <p>RFQ</p>
<p>CP0402A1960ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 454403 pcs</p> <p>RFQ</p>	<p>CP0402A2400FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4GHZ 0402 I roto i te taonga: 505573 pcs</p> <p>RFQ</p>
<p>CP0402A1950DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 474253 pcs</p> <p>RFQ</p>	<p>CP0402A2400ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4GHZ 0402 I roto i te taonga: 513383 pcs</p> <p>RFQ</p>
<p>CP0402A2140ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.14GHZ 0402 I roto i te taonga: 383642 pcs</p> <p>RFQ</p>	<p>CP0402A1960DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 508557 pcs</p> <p>RFQ</p>
<p>CP0402A1950BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 487993 pcs</p> <p>RFQ</p>	<p>CP0402A1950ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 392608 pcs</p> <p>RFQ</p>