



Leader Tech Inc.

55-CBSA-2.25X3.0X0.5

Tau Wae:	55-CBSA-2.25X3.0X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	55 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	55-CBSA-2.25X3.0X0.5.pdf
RoHs Tūnga	Whakahaerehia te kore utu / RoHS
Waehe Stock	4556 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 55-CBSA-2.25X3.0X0.5

TAU WAE	55-CBSA-2.25X3.0X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	55 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4556 pcs
PEPA RARAUNGA	55-CBSA-2.25X3.0X0.5.pdf
WHĀNUI - WHĀNUI	2.250" (57.15mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	55-CBSA-2.25X3.0X0.4 55-CBSA-2.25X3.0X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	3.000" (76.20mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.250" (57.15mm) X 3.000" (76.20mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 55-CBSA-2.25X3.0X0.5	55-CBSA-2.25X3.0X0.5 Kaiwhiwhi	55-CBSA-2.25X3.0X0.5 Kaiwhakarato
55-CBSA-2.25X3.0X0.5 Utu	55-CBSA-2.25X3.0X0.5 Pikitia	55-CBSA-2.25X3.0X0.5 Whakaahua
55-CBSA-2.25X3.0X0.5 PDF Datasheet	55-CBSA-2.25X3.0X0.5 Download Datasheet	Tuhinga 55-CBSA-2.25X3.0X0.5
55-CBSA-2.25X3.0X0.5 Stock	Hokona 55-CBSA-2.25X3.0X0.5	Hokona Leader Tech Inc. 55-CBSA-2.25X3.0X0.5
Leader Tech Inc. 55-CBSA-2.25X3.0X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 55-CBSA-2.25X3.0X0.5		

Ngā Hua e hāngai ana

<p>55-CBSA-2.25X2.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3859 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.25X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3639 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.25X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4780 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.25X2.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5193 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.0X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4045 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.0X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3733 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.25X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3802 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.25X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4150 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.0X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3451 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.25X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4200 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.25X2.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3996 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.25X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4758 pcs</p> <p>RFQ</p>