



Cynergy3

ILLS-G1000-5-015

Tau Wae:

ILLS-G1000-5-015

Kaihanga / Waitohu:

Cynergy3

Whakaahuatanga hua

SENSOR PRESSURE 0-10MWG 4-20MA

Ngā Rauemi:

[ILLS-G1000-5-015.pdf](#)

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

214 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o ILLS-G1000-5-015

TAU WAE	ILLS-G1000-5-015
KAIHANGA	Cynergy3
WHAKAAHUATANGA	SENSOR PRESSURE 0-10MWG 4-20MA
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	214 pcs
PEPA RARAUNGA	ILLS-G1000-5-015.pdf
TE WHAKATAU NGAOHIKO	9 ~ 32 V
MOMO	Liquid
WHAKAWHITIHIHA TE TAUMATA TURE	-
RAUPAPA	ILLS
MOMO PUTANGA	Analog (Diaphragm)
WHIRIHORANGA WHAKAPUTA	4mA ~ 20mA
TAE MAHI	-20°C ~ 60°C
MOMO TAE	Cable Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
RAUEMI - TE WHARE ME TE PRISM	303 Stainless Steel, 316 Stainless Steel
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Liquid Level Sensor Analog (Diaphragm) 4mA ~ 20mA Output Cable Mount

Ngā tūtohu e hāngai ana

Cynergy3 ILLS-G1000-5-015	ILLS-G1000-5-015 Kaiwhiwhi	ILLS-G1000-5-015 Kaiwhakarato
ILLS-G1000-5-015 Utu	ILLS-G1000-5-015 Pikitia	ILLS-G1000-5-015 Whakaahua
ILLS-G1000-5-015 PDF Datasheet	ILLS-G1000-5-015 Download Datasheet	Tuhinga ILLS-G1000-5-015
ILLS-G1000-5-015 Stock	Hokona ILLS-G1000-5-015	Hokona Cynergy3 ILLS-G1000-5-015
Cynergy3 ILLS-G1000-5-015	Cynergy3 Kaiwhakarato	Cynergy3 Kaiwhiwhi
Cynergy3 ILLS-G1000-5-015	Cynergy 3 ILLS-G1000-5-015	

Ngā Hua e hāngai ana

<p>ILLS-G0500-5-007 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-5MWG 4-20MA I roto i te taonga: 338 pcs</p> <p>RFQ</p>	<p>ILLS-G0500-D-007 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-5MWG 0.5-4.5V I roto i te taonga: 332 pcs</p> <p>RFQ</p>
<p>ILLS-G0250-5-005 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-2.5MWG 4-20MA I roto i te taonga: 380 pcs</p> <p>RFQ</p>	<p>ILLSU-GI120-5-005 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRES 0-120"WG 4-20MA 5M I roto i te taonga: 313 pcs</p> <p>RFQ</p>
<p>ILLSU-GI048-5-003 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRES 0-48"WG 4-20MA 3M I roto i te taonga: 324 pcs</p> <p>RFQ</p>	<p>ILLS-G0750-D-010 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-7.5MWG 0.5-4.5 I roto i te taonga: 265 pcs</p> <p>RFQ</p>
<p>ILLSU-GI048-D-003 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRES 0-48"WG 0.5-4.5V 3M I roto i te taonga: 418 pcs</p> <p>RFQ</p>	<p>ILLS-G1000-D-015 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-10MWG 0.5-4.5V I roto i te taonga: 222 pcs</p> <p>RFQ</p>
<p>ILLS-G0750-5-010 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-7.5MWG 4-20MA I roto i te taonga: 294 pcs</p> <p>RFQ</p>	<p>ILLSU-GI120-D-005 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRES 0-120"WG 0.5-4.5V 5M I roto i te taonga: 361 pcs</p> <p>RFQ</p>
<p>ILLS-G0250-D-005 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRESSURE 0-2.5MWG 0.5-4.5 I roto i te taonga: 290 pcs</p> <p>RFQ</p>	<p>ILLSU-GI240-5-008 Kaihanga: Cynergy3 Whakaahuatanga: SENSOR PRES 0-240"WG 4-20MA 8M I roto i te taonga: 317 pcs</p> <p>RFQ</p>

