





AVX Corporation


CP0603D1880BWTR

Tau Wae:	CP0603D1880BWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.85-1.91GHZ 0603
Ngā Rauemi:	 CP0603D1880BWTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	385891 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

[TONO MO TE WHAKAHUA](#)

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CP0603D1880BWTR

TAU WAE	CP0603D1880BWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.85-1.91GHZ 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	385891 pcs
PEPA RARAUNGA	 CP0603D1880BWTR.pdf
PŪRERE PŪRERE WHAKARATO	0603
RAUPAPA	-
HOKI HOKI	27dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-31dB
TE HAINATANGA WHAKATAUNGA	0.55dB
RAUTANGA	1.85GHz ~ 1.91GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 13.5dB 3W 0603 (1608 Metric)
HONONGA TAE	13.5dB
HE MOMO HOAHOA	Standard
NGA TONO	PCS

Ngā tūtohu e hāngai ana

AVX Corporation CP0603D1880BWTR	CP0603D1880BWTR Kaihiwhi	CP0603D1880BWTR Kaiwhakarato
CP0603D1880BWTR Utu	CP0603D1880BWTR Pikitia	CP0603D1880BWTR Whakaahua
CP0603D1880BWTR PDF Datasheet	CP0603D1880BWTR Download Datasheet	Tuhinga CP0603D1880BWTR
CP0603D1880BWTR Stock	Hokona CP0603D1880BWTR	Hokona AVX Corporation CP0603D1880BWTR
AVX Corporation CP0603D1880BWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0603D1880BWTR	AVX Corporation [MIL] CP0603D1880BWTR	

Ngā Hua e hāngai ana

 <p>CP0603D1890BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0603 I roto i te taonga: 385592 pcs</p> <p>RFQ</p>	 <p>CP0603Q5425ENTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.5GHZ 0603 I roto i te taonga: 186665 pcs</p> <p>RFQ</p>
 <p>CP0603V0836CNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 824-849MHZ 0603 I roto i te taonga: 405429 pcs</p> <p>RFQ</p>	 <p>CP0603D3000AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 3GHZ 0603 I roto i te taonga: 429643 pcs</p> <p>RFQ</p>
 <p>CP0603D1441AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.429-1.453GHZ 0603 I roto i te taonga: 344101 pcs</p> <p>RFQ</p>	 <p>CP0603D0897AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 880-915MHZ 0603 I roto i te taonga: 350727 pcs</p> <p>RFQ</p>
 <p>CP0603D0942AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 925-960MHZ 0603 I roto i te taonga: 444819 pcs</p> <p>RFQ</p>	 <p>CP0603D2442AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0603 I roto i te taonga: 389294 pcs</p> <p>RFQ</p>
 <p>CP0603D0947AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 935-960MHZ 0603 I roto i te taonga: 366870 pcs</p> <p>RFQ</p>	 <p>CP0603D2442BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0603 I roto i te taonga: 390239 pcs</p> <p>RFQ</p>
 <p>CP0603D1034AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.034GHZ 0603 I roto i te taonga: 346227 pcs</p> <p>RFQ</p>	 <p>CP0603D0902AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 890-915MHZ 0603 I roto i te taonga: 417000 pcs</p> <p>RFQ</p>