



AVX Corporation

### CP0402A1950FLTR

Tau Wae:

CP0402A1950FLTR

Kaihanga / Waitohu:

AVX Corporation

Whakaahuatanga hua

RF DIR COUPLER 1.9GHZ 0402

Ngā Rauemi:

CP0402A1950FLTR.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waeheere Stock

464652 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o CP0402A1950FLTR

TAU WAE	CP0402A1950FLTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.9GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	464652 pcs
PEPA RARAUNGA	CP0402A1950FLTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
ĒTAHI INGOA	CP0402A1950FL CP0402A1950FL-ND
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	1.9GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 1.9GHz 3W 0402 (1005 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

#### Ngā tūtohu e hāngai ana

AVX Corporation CP0402A1950FLTR	CP0402A1950FLTR Kaiwhiwhi	CP0402A1950FLTR Kaiwhakarato
CP0402A1950FLTR Utu	CP0402A1950FLTR Pikitia	CP0402A1950FLTR Whakaahua
CP0402A1950FLTR PDF Datasheet	CP0402A1950FLTR Download Datasheet	Tuhinga CP0402A1950FLTR
CP0402A1950FLTR Stock	Hokona CP0402A1950FLTR	Hokona AVX Corporation CP0402A1950FLTR
AVX Corporation CP0402A1950FLTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaiwhiwhi
AVX Corporation CP0402A1950FLTR	AVX Corporation [MIL] CP0402A1950FLTR	

#### Ngā Hua e hāngai ana

<p><b>CP0402A1950BLTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 487993 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0402A2140ELTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.14GHZ 0402 I roto i te taonga: 383642 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0402A1960ALTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 433792 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0402A1960ELTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 454403 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0402A2350FLTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.35GHZ 0402 I roto i te taonga: 489817 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0402A1950DLTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 474253 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0402A1950CLTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 486772 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0402A1890ELTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0402 I roto i te taonga: 459521 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0402A1960DLTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 508557 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0402A1950ELTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 392608 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0402A1950ALTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 414676 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0402A1960CNTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 380691 pcs</p> <p><b>RFQ</b></p>

