

Renesas Electronics America

R5F56318CDBG#U0

Tau Wae: R5F56318CDBG#U0
 Kaihanga / Waitohu: Renesas Electronics America
 Whakaahuatanga hua: IC MCU 32BIT 512KB FLASH 176BGA
 Ngā Rauemi: [1.R5F56318CDBG#U0.pdf](#)
[2.R5F56318CDBG#U0.pdf](#)
 RoHs Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 8110 pcs stock
 Tuhianga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o R5F56318CDBG#U0

TAU WAE	R5F56318CDBG#U0
KAIHANGA	Renesas Electronics America
WHAKAAHUATANGA	IC MCU 32BIT 512KB FLASH 176BGA
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	8110 pcs
PEPA RARAUNGA	1.R5F56318CDBG#U0.pdf 2.R5F56318CDBG#U0.pdf
NGAOHIHI - WHAKAAETANGA (VCC / VDD)	2.7 V ~ 3.6 V
PŪRERE PŪRERE WHAKARATO	176-LFBGA (13x13)
TERE	100MHz
RAUPAPA	RX600
RAHI RAM	128K x 8
MOMO MOMO RATONGA	FLASH
RAHI MOTU RATONGA	512KB (512K x 8)
NGA PAPA HANGA REO	DMA, LVD, POR, PWM, WDT
PACKAGING	Tray
PAA / CASE	176-LFBGA
OSCILLATOR MOMO	Internal
TAE MAHI	-40°C ~ 85°C (TA)
TAU O I / O	133
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAE EEPROM	32K x 8
WHAKAAHUATANGA TAIPITOPITO	RX RX600 Microcontroller IC 32-Bit 100MHz 512KB (512K x 8) FLASH 176-LFBGA (13x13)
RARAUNGA RARAUNGA	A/D 8x10b, 21x12b, D/A 2x10b
NUI RAHI	32-Bit
TE TUKATUKA CORE	RX
HONONGA	CANbus, EBI/EMI, I ² C, LINbus, SCI, SPI, USB

Ngā tūtohu e hāngai ana

Renesas Electronics America R5F56318CDBG#U0	R5F56318CDBG#U0 Kaiwhiwhi	R5F56318CDBG#U0 Kaiwhakarato
R5F56318CDBG#U0 Utu	R5F56318CDBG#U0 Pikitia	R5F56318CDBG#U0 Whakaahua
R5F56318CDBG#U0 PDF Datasheet	R5F56318CDBG#U0 Download Datasheet	Tuhinga R5F56318CDBG#U0
R5F56318CDBG#U0 Stock	Hokona R5F56318CDBG#U0	Hokona Renesas Electronics America R5F56318CDBG#U0
Renesas Electronics America R5F56318CDBG#U0	Renesas Electronics America Kaiwhakarato	Renesas Electronics America Kaiwhiwhi
Renesas Electronics America R5F56318CDBG#U0	Renesas Technology Corp R5F56318CDBG#U0	Renesas R5F56318CDBG#U0

Ngā Hua e hāngai ana

<p>R5F56317DDLK#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 384KB FLASH 145LGA I roto i te taonga: 9462 pcs</p> <p>RFQ</p>	<p>R5F56318CDLC#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 177LGA I roto i te taonga: 9635 pcs</p> <p>RFQ</p>
<p>R5F56317SDLK#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 384KB FLASH 145LGA I roto i te taonga: 10043 pcs</p> <p>RFQ</p>	<p>R5F56317SDFC#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 384KB FLASH 176QFP I roto i te taonga: 8708 pcs</p> <p>RFQ</p>
<p>R5F56318CDFP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 100LQFP I roto i te taonga: 10585 pcs</p> <p>RFQ</p>	<p>R5F56318CDLK#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 145LGA I roto i te taonga: 8310 pcs</p> <p>RFQ</p>
<p>R5F56318CDFB#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 144QFP I roto i te taonga: 9775 pcs</p> <p>RFQ</p>	<p>R5F56317SDBG#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 384KB FLASH 176BGA I roto i te taonga: 10536 pcs</p> <p>RFQ</p>
<p>R5F56318CDFC#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 176QFP I roto i te taonga: 8556 pcs</p> <p>RFQ</p>	<p>R5F56318CDLJ#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 100LGA I roto i te taonga: 12046 pcs</p> <p>RFQ</p>
<p>R5F56317SDFB#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 384KB FLASH 144QFP I roto i te taonga: 10634 pcs</p> <p>RFQ</p>	<p>R5F56317SDLC#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 384KB FLASH 177LGA I roto i te taonga: 10750 pcs</p> <p>RFQ</p>