

TAIYO YUDEN Taiyo Yuden

D6HH1G960BH95-Z

Tau Wae:	D6HH1G960BH95-Z
Kaihanga / Waitohu:	Taiyo Yuden
Whakaahuatanga hua	RF DIPLEXER 9SMD NO LEAD
Ngā Rauemi:	D6HH1G960BH95-Z.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	22526 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o D6HH1G960BH95-Z

TAU WAE	D6HH1G960BH95-Z
KAIHANGA	Taiyo Yuden
WHAKAAHUATANGA	RF DIPLEXER 9SMD NO LEAD
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	22526 pcs
PEPA RARAUNGA	D6HH1G960BH95-Z.pdf
RAUPAPA	D6
PACKAGING	Cut Tape (CT)
PAA / CASE	9-SMD, No Lead
ĒTAHI INGOA	587-3004-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 9-SMD, No Lead

Ngā tūtohu e hāngai ana

Taiyo Yuden D6HH1G960BH95-Z	D6HH1G960BH95-Z Kaiwhiwhi	D6HH1G960BH95-Z Kaiwhakarato
D6HH1G960BH95-Z Utu	D6HH1G960BH95-Z Pikitia	D6HH1G960BH95-Z Whakaahua
D6HH1G960BH95-Z PDF Datasheet	D6HH1G960BH95-Z Download Datasheet	Tuhinga D6HH1G960BH95-Z
D6HH1G960BH95-Z Stock	Hokona D6HH1G960BH95-Z	Hokona Taiyo Yuden D6HH1G960BH95-Z
Taiyo Yuden D6HH1G960BH95-Z	Taiyo Yuden Kaiwhakarato	Taiyo Yuden Kaiwhiwhi
Taiyo Yuden D6HH1G960BH95-Z		

Ngā Hua e hāngai ana

<p>D6HL2G655DL09-Z Kaihanga: Taiyo Yuden Whakaahuatanga: FBAR DUPLEXER 2016 CSSD BAND 7 I roto i te taonga: 58299 pcs</p> <p>RFQ</p>	<p>FI168P157525-T Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 892MHZ/1.584GHZ 0603 I roto i te taonga: 119417 pcs</p> <p>RFQ</p>
<p>DIP2450-01D3 Kaihanga: STMicroelectronics Whakaahuatanga: RF DIPLEXER 2.4415/5.375GHZ 4BGA I roto i te taonga: 221973 pcs</p> <p>RFQ</p>	<p>D6HQ2G655DP02-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 1GHZ-5GHZ 8SMD I roto i te taonga: 43889 pcs</p> <p>RFQ</p>
<p>D6HL1G960DL33-Z Kaihanga: Taiyo Yuden Whakaahuatanga: FBAR DUPLEXER 2016 CSSD B2 I roto i te taonga: 61399 pcs</p> <p>RFQ</p>	<p>D6HN2G655BN54-Z Kaihanga: Taiyo Yuden Whakaahuatanga: FBAR DUPLEXER 2016 CSSD BAND 7 B I roto i te taonga: 47185 pcs</p> <p>RFQ</p>
<p>D6HK1G960DK12-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 9SMD NO LEAD I roto i te taonga: 65758 pcs</p> <p>RFQ</p>	<p>D6HP2G655BP11-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 8SMD NO LEAD I roto i te taonga: 52571 pcs</p> <p>RFQ</p>
<p>D6HL2G655DL06-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 2.535/2.655GHZ 9SMD I roto i te taonga: 48089 pcs</p> <p>RFQ</p>	<p>DPX165950DT-8144A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD I roto i te taonga: 63461 pcs</p> <p>RFQ</p>
<p>D6HQ1G962DP39-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 1.8825/1.962GHZ 8SMD I roto i te taonga: 21426 pcs</p> <p>RFQ</p>	<p>D6HL1G962DL39-Z Kaihanga: Taiyo Yuden Whakaahuatanga: FBAR DUPLEXER 2016 CSSD BAND 25 I roto i te taonga: 50360 pcs</p> <p>RFQ</p>