



Leader Tech Inc.

55-CBSA-2.75X4.5X0.5

Tau Wae:	55-CBSA-2.75X4.5X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	55 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	55-CBSA-2.75X4.5X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3802 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 55-CBSA-2.75X4.5X0.5

TAU WAE	55-CBSA-2.75X4.5X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	55 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3802 pcs
PEPA RARAUNGA	55-CBSA-2.75X4.5X0.5.pdf
WHĀNUI - WHĀNUI	2.750" (69.85mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	55-CBSA-2.75X4.5X0.4 55-CBSA-2.75X4.5X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	4.500" (114.30mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.750" (69.85mm) X 4.500" (114.30mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 55-CBSA-2.75X4.5X0.5	55-CBSA-2.75X4.5X0.5 Kaiwhiwhi	55-CBSA-2.75X4.5X0.5 Kaiwhakarato
55-CBSA-2.75X4.5X0.5 Utu	55-CBSA-2.75X4.5X0.5 Pikitia	55-CBSA-2.75X4.5X0.5 Whakaahua
55-CBSA-2.75X4.5X0.5 PDF Datasheet	55-CBSA-2.75X4.5X0.5 Download Datasheet	Tuhinga 55-CBSA-2.75X4.5X0.5
55-CBSA-2.75X4.5X0.5 Stock	Hokona 55-CBSA-2.75X4.5X0.5	Hokona Leader Tech Inc. 55-CBSA-2.75X4.5X0.5
Leader Tech Inc. 55-CBSA-2.75X4.5X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 55-CBSA-2.75X4.5X0.5		

Ngā Hua e hāngai ana

<p>55-CBSA-2.75X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3656 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.75X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3281 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.75X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3710 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.75X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3198 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.75X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4305 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.75X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3945 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.75X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3961 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.75X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3298 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.75X3.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4669 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.75X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3121 pcs</p> <p>RFQ</p>
<p>55-CBSA-2.75X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3458 pcs</p> <p>RFQ</p>	<p>55-CBSA-2.75X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 55 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3319 pcs</p> <p>RFQ</p>