





AVX Corporation


## CP0805B1975CWTR

Tau Wae:	CP0805B1975CWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.975GHZ 0805
Ngā Rauemi:	 CP0805B1975CWTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	287903 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













### Ngā whakaaturanga o CP0805B1975CWTR

TAU WAE	CP0805B1975CWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.975GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	287903 pcs
PEPA RARAUNGA	 CP0805B1975CWTR.pdf
PŪRERE PŪRERE WHAKARATO	0805
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	1.975GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 1.975GHz 3W 0805 (2012 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

### Ngā tūtohu e hāngai ana

AVX Corporation CP0805B1975CWTR	CP0805B1975CWTR Kaihiwhi	CP0805B1975CWTR Kaiwhakarato
CP0805B1975CWTR Utu	CP0805B1975CWTR Pikitia	CP0805B1975CWTR Whakaahua
CP0805B1975CWTR PDF Datasheet	CP0805B1975CWTR Download Datasheet	Tuhinga CP0805B1975CWTR
CP0805B1975CWTR Stock	Hokona CP0805B1975CWTR	Hokona AVX Corporation CP0805B1975CWTR
AVX Corporation CP0805B1975CWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0805B1975CWTR	AVX Corporation [MIL] CP0805B1975CWTR	

### Ngā Hua e hāngai ana

 <p><b>CP0805B2442AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 305089 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0805B1960BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0805 I roto i te taonga: 265980 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0805B1907BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.895-1.92GHZ 0805 I roto i te taonga: 292009 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0805B2442BW</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 212192 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0805B1950CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.95GHZ 0805 I roto i te taonga: 311049 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0805B2442BSTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 236270 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0805B1916CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.916GHZ 0805 I roto i te taonga: 277806 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0805B2140CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.14GHZ 0805 I roto i te taonga: 292640 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0805B2442CW</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 6987 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0805B1960CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0805 I roto i te taonga: 266809 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0805B1960AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0805 I roto i te taonga: 239843 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0805B2442BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 80225 pcs</p> <p><b>RFQ</b></p>