



TDK Corporation

## DPX165950DT-8118A1

Tau Wae:	DPX165950DT-8118A1
Kaihanga / Waitohu:	TDK Corporation
Whakaahuatanga hua	RF DIPLEXER 2.45/5.425GHZ 0603
Ngā Rauemi:	DPX165950DT-8118A1.pdf
RoHs Tūnga	Whakahaerehia te kore utu / RoHS
Waeheere Stock	345480 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o DPX165950DT-8118A1

TAU WAE	DPX165950DT-8118A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	RF DIPLEXER 2.45/5.425GHZ 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	345480 pcs
PEPA RARAUNGA	DPX165950DT-8118A1.pdf
RAUPAPA	DPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	9.5dB / 9.5dB
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric), 4 PC Pad
ĒTAHI INGOA	445-15631-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	20.00dB / 23.00dB
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	20.00dB / 27.00dB
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	2.4GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 2.4GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz 0603 (1608 Metric), 4 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation DPX165950DT-8118A1	DPX165950DT-8118A1 Kaiwhiwhi	DPX165950DT-8118A1 Kaiwhakarato
DPX165950DT-8118A1 Utu	DPX165950DT-8118A1 Pikitia	DPX165950DT-8118A1 Whakaahua
DPX165950DT-8118A1 PDF Datasheet	DPX165950DT-8118A1 Download Datasheet	Tuhinga DPX165950DT-8118A1
DPX165950DT-8118A1 Stock	Hokona DPX165950DT-8118A1	Hokona TDK Corporation DPX165950DT-8118A1
TDK Corporation DPX165950DT-8118A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation DPX165950DT-8118A1		

### Ngā Hua e hāngai ana

<p><b>DPX165950DT-8045A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 671865 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8148A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 256554 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165950DT-8126A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 280291 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8060A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 286629 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX2-20745-8</b> Kaihanga: Cannon Whakaahuatanga: RP DPX STRAIGHT JUNCTION SHEL I roto i te taonga: 714 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8030D1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEX 1740.5MZ/5.425GHZ 0603 I roto i te taonga: 350649 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165950DT-8144A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD I roto i te taonga: 63461 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8130A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 325254 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165950DT-8060C1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD I roto i te taonga: 286843 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX165950DT-8048A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 311726 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX165950DT-8030A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 114140 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX2012LL85R2455A</b> Kaihanga: Yageo Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 179376 pcs</p> <p><b>RFQ</b></p>

