





AVX Corporation


## CP0603D2442BWTR

Tau Wae:	CP0603D2442BWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 2.4-2.484GHZ 0603
Ngā Rauemi:	 CP0603D2442BWTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	390239 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o CP0603D2442BWTR

TAU WAE	CP0603D2442BWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 2.4-2.484GHZ 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	390239 pcs
PEPA RARAUNGA	 CP0603D2442BWTR.pdf
PŪRERE PŪRERE WHAKARATO	0603
RAUPAPA	-
HOKI HOKI	24dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-29dB
TE HAINATANGA WHAKATAUNGA	0.7dB
RAUTANGA	2.4GHz ~ 2.484GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler Wireless LAN 2.4GHz ~ 2.484GHz 11dB 3W 0603 (1608 Metric)
HONONGA TAE	11dB
HE MOMO HOAHOA	Standard
NGA TONO	Wireless LAN

### Ngā tūtohu e hāngai ana

AVX Corporation CP0603D2442BWTR	CP0603D2442BWTR Kaihiwhi	CP0603D2442BWTR Kaiwhakarato
CP0603D2442BWTR Utu	CP0603D2442BWTR Pikitia	CP0603D2442BWTR Whakaahua
CP0603D2442BWTR PDF Datasheet	CP0603D2442BWTR Download Datasheet	Tuhinga CP0603D2442BWTR
CP0603D2442BWTR Stock	Hokona CP0603D2442BWTR	Hokona AVX Corporation CP0603D2442BWTR
AVX Corporation CP0603D2442BWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0603D2442BWTR	AVX Corporation [MIL] CP0603D2442BWTR	

### Ngā Hua e hāngai ana

 <p><b>CP0603D0947AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 935-960MHZ 0603 I roto i te taonga: 366870 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0603D1034AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.034GHZ 0603 I roto i te taonga: 346227 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0603D3000AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 3GHZ 0603 I roto i te taonga: 429643 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0603V0836CNTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 824-849MHZ 0603 I roto i te taonga: 405429 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0763-000</b> Kaihanga: Agastat Relays / TE Connectivity Whakaahuatanga: I/O CONN I roto i te taonga: 203 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0603V1880BNTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0603 I roto i te taonga: 408143 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0603D1890BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0603 I roto i te taonga: 385592 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0603D2442AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0603 I roto i te taonga: 389294 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0762-000</b> Kaihanga: Agastat Relays / TE Connectivity Whakaahuatanga: I/O CONN I roto i te taonga: 175 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0603D1441AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.429-1.453GHZ 0603 I roto i te taonga: 344101 pcs</p> <p><b>RFQ</b></p>
 <p><b>CP0603Q5425ENTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.5GHZ 0603 I roto i te taonga: 186665 pcs</p> <p><b>RFQ</b></p>	 <p><b>CP0603D1880BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0603 I roto i te taonga: 385891 pcs</p> <p><b>RFQ</b></p>