



TDK Corporation

TPX205950MT-7010A1

Tau Wae: TPX205950MT-7010A1
 Kaihanga / Waitohu: TDK Corporation
 Whakaahuatanga hua: RF DIPLEXER 2.45/5.425GHZ 0805
 Ngā Rauemi: TPX205950MT-7010A1.pdf
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 515463 pcs stock
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o TPX205950MT-7010A1

TAU WAE	TPX205950MT-7010A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	RF DIPLEXER 2.45/5.425GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	515463 pcs
PEPA RARAUNGA	TPX205950MT-7010A1.pdf
RAUPAPA	TPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	-
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric), 6 PC Pad
ĒTAHI INGOA	445-174756-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	13.00dB / 23.00dB
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	5.00dB / 32.00dB
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	2.4GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 2.4GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz 0805 (2012 Metric), 6 PC Pad

Ngā tūtohu e hāngai ana

TDK Corporation TPX205950MT-7010A1	TPX205950MT-7010A1 Kaihiwhi	TPX205950MT-7010A1 Kaiwhakarato
TPX205950MT-7010A1 Utu	TPX205950MT-7010A1 Pikitia	TPX205950MT-7010A1 Whakaahua
TPX205950MT-7010A1 PDF Datasheet	TPX205950MT-7010A1 Download Datasheet	Tuhinga TPX205950MT-7010A1
TPX205950MT-7010A1 Stock	Hokona TPX205950MT-7010A1	Hokona TDK Corporation TPX205950MT-7010A1
TDK Corporation TPX205950MT-7010A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaihiwhi
TDK Corporation TPX205950MT-7010A1		

Ngā Hua e hāngai ana

<p>DPX165850DT-8132A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0603 4 PC PAD I roto i te taonga: 103713 pcs</p> <p>RFQ</p>	<p>D6PF1G960M3B6-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 9SMD NO LEAD I roto i te taonga: 35784 pcs</p> <p>RFQ</p>
<p>TPX205950MT-7110A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 605046 pcs</p> <p>RFQ</p>	<p>B39212B8550P810S5 Kaihanga: Epcos / RF360 Whakaahuatanga: SAW DUPLEXER MOBILE SMD I roto i te taonga: 5095 pcs</p> <p>RFQ</p>
<p>D5PF942M5M3G9-Z Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 9SMD NO LEAD I roto i te taonga: 76761 pcs</p> <p>RFQ</p>	<p>FI212P0829G2-T Kaihanga: Taiyo Yuden Whakaahuatanga: RF DIPLEXER 829MHZ/2.2GHZ 0603 I roto i te taonga: 111673 pcs</p> <p>RFQ</p>
<p>TPX255850MT-7013A3 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1008 9 PC PAD I roto i te taonga: 195838 pcs</p> <p>RFQ</p>	<p>CX6167NL Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 6483 pcs</p> <p>RFQ</p>
<p>DPX165950DT-8144A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD I roto i te taonga: 63461 pcs</p> <p>RFQ</p>	<p>SD25-0836L8UU11 Kaihanga: AVX Corporation Whakaahuatanga: RF DIPLEXER 836.5/881.5MHZ 8SMD I roto i te taonga: 5151 pcs</p> <p>RFQ</p>
<p>B39851B8081P810 Kaihanga: Epcos / RF360 Whakaahuatanga: RF DIPLEXER 847MHZ/806MHZ 9SMD I roto i te taonga: 4504 pcs</p> <p>RFQ</p>	<p>TPX205950MT-7004A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 579309 pcs</p> <p>RFQ</p>

