



Aeroflex (MACOM Technology Solutions)

## MACP-010563-001SMB

Tau Wae: MACP-010563-001SMB  
 Kaihanga / Waitohu: Aeroflex (MACOM Technology Solutions)  
 Whakaahuatanga hua: EVAL BOARD FOR MACP-010563-TR100  
 Ngā Rauemi:  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Waehere Stock: 4608 pcs stock  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

### Solutions



Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o MACP-010563-001SMB

TAU WAE	MACP-010563-001SMB
KAIHANGA	Aeroflex (MACOM Technology Solutions)
WHAKAAHUATANGA	EVAL BOARD FOR MACP-010563-TR100
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4608 pcs
PEPA RARAUNGA	
MOMO	Power Detector
TUHINGA KUA WHAKARATOHIA	Board(s)
RAUPAPA	-
ĒTAHI INGOA	1465-1580
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAUTANGA	10GHz ~ 30GHz
MO TE WHAKAMAHI ME TE / PRODUCTS RELATED	MACP-010563

### Ngā tūtohu e hāngai ana

Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	MACP-010563-001SMB Kaiwhiwhi	MACP-010563-001SMB Kaiwhakarato
MACP-010563-001SMB Utu	MACP-010563-001SMB Pikitia	MACP-010563-001SMB Whakaahua
MACP-010563-001SMB PDF Datasheet	MACP-010563-001SMB Download Datasheet	Tuhinga MACP-010563-001SMB
MACP-010563-001SMB Stock	Hokona MACP-010563-001SMB	Hokona Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB
Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	Aeroflex (MACOM Technology Solutions) Kaiwhakarato	Aeroflex (MACOM Technology Solutions) Kaiwhiwhi
Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	Aeroflex Circuit Technology MACP-010563-001SMB	Aeroflex MACP-010563-001SMB
Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	Aeroflex Metelics, Division of MACOM MACP-010563-001SMB	M/A-Com Technology Solutions MACP-010563-001SMB
Metelics (MACOM Technology Solutions) MACP-010563-001SMB	MACOM Technology Solutions MACP-010563-001SMB	

### Ngā Hua e hāngai ana

<p><b>MACP-010562-000000</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 6GHZ-18GHZ 6TDFN                  I roto i te taonga: 4595 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010563-TR1000</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 10GHZ-30GHZ 6TDFN                  I roto i te taonga: 4446 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-010561-TR1000</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 2GHZ-6GHZ 6DFN                  I roto i te taonga: 4662 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010561-001SMB</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: EVAL BOARD FOR MACP-010561-TR100                  I roto i te taonga: 3678 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011032</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD                  I roto i te taonga: 33983 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010562-001SMB</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: EVAL BOARD FOR MACP-010562-TR100                  I roto i te taonga: 5017 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011010</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD                  I roto i te taonga: 69745 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-010562-TR1000</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 6GHZ-18GHZ 6TDFN                  I roto i te taonga: 3016 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-010563-000000</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 10GHZ-30GHZ 6TDFN                  I roto i te taonga: 6556 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011015</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD                  I roto i te taonga: 24969 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011014</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD                  I roto i te taonga: 34558 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011013</b>                  Kaihanga: Aeroflex (MACOM Technology Solutions)                  Whakaahuatanga: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD                  I roto i te taonga: 75305 pcs</p> <p><b>RFQ</b></p>

