





AVX Corporation


CP0402A3200ALTR

Tau Wae:	CP0402A3200ALTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 3.2GHZ 0402
Ngā Rauemi:	 CP0402A3200ALTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waeheere Stock	494774 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.












Ngā whakaaturanga o CP0402A3200ALTR

TAU WAE	CP0402A3200ALTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 3.2GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	494774 pcs
PEPA RARAUNGA	 CP0402A3200ALTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	3.2GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 3.2GHz 3W 0402 (1005 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

Ngā tūtohu e hāngai ana

AVX Corporation CP0402A3200ALTR	CP0402A3200ALTR Kaihiwhi	CP0402A3200ALTR Kaiwhakarato
CP0402A3200ALTR Utu	CP0402A3200ALTR Pikitia	CP0402A3200ALTR Whakaahua
CP0402A3200ALTR PDF Datasheet	CP0402A3200ALTR Download Datasheet	Tuhinga CP0402A3200ALTR
CP0402A3200ALTR Stock	Hokona CP0402A3200ALTR	Hokona AVX Corporation CP0402A3200ALTR
AVX Corporation CP0402A3200ALTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0402A3200ALTR	AVX Corporation [MIL] CP0402A3200ALTR	

Ngā Hua e hāngai ana

 <p>CP0402A2442FNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0402 I roto i te taonga: 472810 pcs</p> <p>RFQ</p>	 <p>CP0402A3500FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 3.5GHZ 0402 I roto i te taonga: 460606 pcs</p> <p>RFQ</p>
 <p>CP0402A3600BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 3.6GHZ 0402 I roto i te taonga: 426795 pcs</p> <p>RFQ</p>	 <p>CP0402A4600ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 4.6GHZ 0402 I roto i te taonga: 495470 pcs</p> <p>RFQ</p>
 <p>CP0402A4200ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 4.2GHZ 0402 I roto i te taonga: 385273 pcs</p> <p>RFQ</p>	 <p>CP0402A3500ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 3.5GHZ 0402 I roto i te taonga: 499070 pcs</p> <p>RFQ</p>
 <p>CP0402A2400ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4GHZ 0402 I roto i te taonga: 513383 pcs</p> <p>RFQ</p>	 <p>CP0402A2442ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0402 I roto i te taonga: 468727 pcs</p> <p>RFQ</p>
 <p>CP0402A2400FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4GHZ 0402 I roto i te taonga: 505573 pcs</p> <p>RFQ</p>	 <p>CP0402A5250FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 5.25GHZ 0402 I roto i te taonga: 443929 pcs</p> <p>RFQ</p>
 <p>CP0402A2442ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0402 I roto i te taonga: 409460 pcs</p> <p>RFQ</p>	 <p>CP0402A2442FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0402 I roto i te taonga: 436194 pcs</p> <p>RFQ</p>