





AVX Corporation


CP0805B2442AWTR

Tau Wae:	CP0805B2442AWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 2.4-2.484GHZ 0805
Ngā Rauemi:	 CP0805B2442AWTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waeheere Stock	305089 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o CP0805B2442AWTR

TAU WAE	CP0805B2442AWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 2.4-2.484GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	305089 pcs
PEPA RARAUNGA	 CP0805B2442AWTR.pdf
PŪRERE PŪRERE WHAKARATO	0805
RAUPAPA	-
HOKI HOKI	-23dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-24dB
TE HAINATANGA WHAKATAUNGA	0.4dB
RAUTANGA	2.4GHz ~ 2.484GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler Wireless LAN 2.4GHz ~ 2.484GHz 13 ± 1dB 3W 0805 (2012 Metric)
HONONGA TAE	13 ± 1dB
HE MOMO HOAHOA	Standard
NGA TONO	Wireless LAN

Ngā tūtohu e hāngai ana

AVX Corporation CP0805B2442AWTR	CP0805B2442AWTR Kaihiwhi	CP0805B2442AWTR Kaiwhakarato
CP0805B2442AWTR Utu	CP0805B2442AWTR Pikitia	CP0805B2442AWTR Whakaahua
CP0805B2442AWTR PDF Datasheet	CP0805B2442AWTR Download Datasheet	Tuhinga CP0805B2442AWTR
CP0805B2442AWTR Stock	Hokona CP0805B2442AWTR	Hokona AVX Corporation CP0805B2442AWTR
AVX Corporation CP0805B2442AWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0805B2442AWTR	AVX Corporation [MIL] CP0805B2442AWTR	

Ngā Hua e hāngai ana

 <p>CP0805B2442BW Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 212192 pcs</p> <p>RFQ</p>	 <p>CP0805B2442BSTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 236270 pcs</p> <p>RFQ</p>
 <p>CP0805B2140CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.14GHZ 0805 I roto i te taonga: 292640 pcs</p> <p>RFQ</p>	 <p>CP0805B1975CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.975GHZ 0805 I roto i te taonga: 287903 pcs</p> <p>RFQ</p>
 <p>CP0805B1960AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0805 I roto i te taonga: 239843 pcs</p> <p>RFQ</p>	 <p>CP0805B1950CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.95GHZ 0805 I roto i te taonga: 311049 pcs</p> <p>RFQ</p>
 <p>CP0805B244BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 244MHZ 0805 I roto i te taonga: 5741 pcs</p> <p>RFQ</p>	 <p>CP0805B1960BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0805 I roto i te taonga: 265980 pcs</p> <p>RFQ</p>
 <p>CP0805B2442CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 253709 pcs</p> <p>RFQ</p>	 <p>CP0805B2442CW Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 6987 pcs</p> <p>RFQ</p>
 <p>CP0805B1960CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0805 I roto i te taonga: 266809 pcs</p> <p>RFQ</p>	 <p>CP0805B2442BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0805 I roto i te taonga: 80225 pcs</p> <p>RFQ</p>