



MaxBotix Inc.

MB7586-100

Tau Wae:

MB7586-100

Kaihanga / Waitohu:

MaxBotix Inc.

Whakaahuatanga hua

ULTRASONIC SENSOR SCXL-MAXSONAR

Ngā Rauemi:

MB7586-100.pdf

RoHS Tūnga

RoHS Compliant

Waehere Stock

617 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o MB7586-100

TAU WAE	MB7586-100
KAIHANGA	MaxBotix Inc.
WHAKAAHUATANGA	ULTRASONIC SENSOR SCXL-MAXSONAR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	RoHS Compliant
HE RAHINGA KEI TE WĀTEA	617 pcs
PEPA RARAUNGA	MB7586-100.pdf
PUTANGA - KUA TOHUA	2.5 V ~ 5.5 V
RAUPAPA	SCXL-MaxSonar-WR
ROHS TŪNGA	RoHS Compliant
PACKAGING	Bulk
ĒTAHI INGOA	1863-1071
TAE MAHI	-40°C ~ 65°C (TA)
RAUTANGA	42kHz
WHAKAAHUATANGA TAIPITOPITO	Ultrasonic Sensor 42kHz
TE PEE MAAMA	11°

Ngā tūtohu e hāngai ana

MaxBotix Inc. MB7586-100	MB7586-100 Kaiwhiwhi	MB7586-100 Kaiwhakarato
MB7586-100 Utu	MB7586-100 Pikitia	MB7586-100 Whakaahua
MB7586-100 PDF Datasheet	MB7586-100 Download Datasheet	Tuhinga MB7586-100
MB7586-100 Stock	Hokona MB7586-100	Hokona MaxBotix Inc. MB7586-100
MaxBotix Inc. MB7586-100	MaxBotix Inc. Kaiwhakarato	MaxBotix Inc. Kaiwhiwhi
MaxBotix Inc. MB7586-100		

Ngā Hua e hāngai ana

<p>MB7586-111 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 350 pcs</p> <p>RFQ</p>	<p>MB7586-101 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 393 pcs</p> <p>RFQ</p>
<p>MB7586-121 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 337 pcs</p> <p>RFQ</p>	<p>MB7584-821 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 261 pcs</p> <p>RFQ</p>
<p>MB7586-110 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 400 pcs</p> <p>RFQ</p>	<p>MB7584-810 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 376 pcs</p> <p>RFQ</p>
<p>MB7584-830 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 324 pcs</p> <p>RFQ</p>	<p>MB7586-120 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 433 pcs</p> <p>RFQ</p>
<p>MB7586-130 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 427 pcs</p> <p>RFQ</p>	<p>MB7584-811 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 237 pcs</p> <p>RFQ</p>
<p>MB7584-820 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 374 pcs</p> <p>RFQ</p>	<p>MB7584-831 Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 278 pcs</p> <p>RFQ</p>