

OmniVision. OmniVision Technologies

OV02740-H34A

Tau Wae:	OV02740-H34A
Kaihanga / Waitohu:	OmniVision Technologies
Whakaahuatanga hua	PURECEL (FHD) IMAGE SENSOR
Ngā Rauemi:	OV02740-H34A.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	46584 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o OV02740-H34A

TAU WAE	OV02740-H34A
KAIHANGA	OmniVision Technologies
WHAKAAHUATANGA	PURECEL (FHD) IMAGE SENSOR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	46584 pcs
PEPA RARAUNGA	OV02740-H34A.pdf
TUHINGA O MUA	2.8V
MOMO	CMOS with Processor
PŪRERE PŪRERE WHAKARATO	34-CSP5 (3.85x2.92)
RAUPAPA	PureCel®
RAHI PIKA	1.4µm x 1.4µm
PACKAGING	Tray
PAA / CASE	34-BGA Module
ĒTAHI INGOA	OV2740-H34A OV2740-H34A-ND Q9275500C
TAE MAHI	-30°C ~ 85°C (TJ)
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MAHERE TUARUA	60
WHAKAAHUATANGA TAIPITOPITO	CMOS with Processor Image Sensor 1920H x 1080V 1.4µm x 1.4µm 34-CSP5 (3.85x2.92)
PIHANGA PIKA MAHI	1920H x 1080V

Ngā tūtohu e hāngai ana

OmniVision Technologies OV02740-H34A	OV02740-H34A Kaiwhiwhi	OV02740-H34A Kaiwhakarato
OV02740-H34A Utu	OV02740-H34A Pikitia	OV02740-H34A Whakaahua
OV02740-H34A PDF Datasheet	OV02740-H34A Download Datasheet	Tuhinga OV02740-H34A
OV02740-H34A Stock	Hokona OV02740-H34A	Hokona OmniVision Technologies OV02740-H34A
OmniVision Technologies OV02740-H34A	OmniVision Technologies Kaiwhakarato	OmniVision Technologies Kaiwhiwhi
OmniVision Technologies OV02740-H34A	OmniVision Technologies Inc OV02740-H34A	

Ngā Hua e hāngai ana

<p>OV02735-H66H-1B Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR 66-CSP6 I roto i te taonga: 17351 pcs</p> <p>RFQ</p>	<p>OV02770-H77A-1C Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 8562 pcs</p> <p>RFQ</p>
<p>OV02735-H66A-1B Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR 66-CSP5 I roto i te taonga: 25299 pcs</p> <p>RFQ</p>	<p>OV02A10-GA4A Kaihanga: OmniVision Technologies Whakaahuatanga: PROTOTYPING MODULE CSP I roto i te taonga: 75594 pcs</p> <p>RFQ</p>
<p>OV02A10-A41A Kaihanga: OmniVision Technologies Whakaahuatanga: PROTOTYPING MODULE CSP I roto i te taonga: 77894 pcs</p> <p>RFQ</p>	<p>OV02740-EAAA-AA0A Kaihanga: OmniVision Technologies Whakaahuatanga: PROTO MODULE FOR 1080P HD CSP I roto i te taonga: 680 pcs</p> <p>RFQ</p>
<p>OV02735-H66A Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 21337 pcs</p> <p>RFQ</p>	<p>OV03640-ECJA-BA0A Kaihanga: OmniVision Technologies Whakaahuatanga: KIT EVAL FOR OV03640 3MP I roto i te taonga: 5958 pcs</p> <p>RFQ</p>
<p>OV02742-GA5A Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 32338 pcs</p> <p>RFQ</p>	<p>OV02740-GA4A Kaihanga: OmniVision Technologies Whakaahuatanga: IC IMAGE SENSOR 1080P/60 HD RW I roto i te taonga: 53768 pcs</p> <p>RFQ</p>
<p>OV02736-H46A Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 16412 pcs</p> <p>RFQ</p>	<p>OV02770-H77A-PC Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 7142 pcs</p> <p>RFQ</p>