



OmniVision Technologies

OV02722-G04A

Tau Wae:	OV02722-G04A
Kaihanga / Waitohu:	OmniVision Technologies
Whakaahuatanga hua	IC IMAGE SENSOR 1080P RW
Ngā Rauemi:	
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	27960 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o OV02722-G04A

TAU WAE	OV02722-G04A
KAIHANGA	OmniVision Technologies
WHAKAAHUATANGA	IC IMAGE SENSOR 1080P RW
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	27960 pcs
PEPA RARAUNGA	
TUHINGA O MUA	2.8V
MOMO	CMOS with Processor
PŪRERE PŪRERE WHAKARATO	Module
RAUPAPA	CameraChip™, OmniBSI+™
RAHI PIKA	1.4µm x 1.4µm
PACKAGING	Bulk
PAA / CASE	Module
TAE MAHI	-20°C ~ 70°C (TJ)
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MAHERE TUARUA	30
WHAKAAHUATANGA TAIPITOPITO	CMOS with Processor Image Sensor 1932H x 1092V 1.4µm x 1.4µm Module
PIHANGA PIKA MAHI	1932H x 1092V

Ngā tūtohu e hāngai ana

OmniVision Technologies OV02722-G04A	OV02722-G04A Kaiwhiwhi	OV02722-G04A Kaiwhakarato
OV02722-G04A Utu	OV02722-G04A Pikitia	OV02722-G04A Whakaahua
OV02722-G04A PDF Datasheet	OV02722-G04A Download Datasheet	Tuhinga OV02722-G04A
OV02722-G04A Stock	Hokona OV02722-G04A	Hokona OmniVision Technologies OV02722-G04A
OmniVision Technologies OV02722-G04A	OmniVision Technologies Kaiwhakarato	OmniVision Technologies Kaiwhiwhi
OmniVision Technologies OV02722-G04A	OmniVision Technologies Inc OV02722-G04A	

Ngā Hua e hāngai ana

<p>OV02718-H77T-2A Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR 77-CSP5 I roto i te taonga: 12573 pcs</p> <p>RFQ</p>	<p>OV02724-G04A Kaihanga: OmniVision Technologies Whakaahuatanga: IC IMAGE SENSOR 1080P RW I roto i te taonga: 44465 pcs</p> <p>RFQ</p>
<p>OV02736-H46A Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 16412 pcs</p> <p>RFQ</p>	<p>OV02732-H46A-1B Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 18649 pcs</p> <p>RFQ</p>
<p>OV02735-H66H-1B Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR 66-CSP6 I roto i te taonga: 17351 pcs</p> <p>RFQ</p>	<p>OV02718-H77A-PA Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR I roto i te taonga: 11391 pcs</p> <p>RFQ</p>
<p>OV02735-H66A-1B Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR 66-CSP5 I roto i te taonga: 25299 pcs</p> <p>RFQ</p>	<p>OV02718-H77T Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR I roto i te taonga: 13681 pcs</p> <p>RFQ</p>
<p>OV02722-A50A Kaihanga: OmniVision Technologies Whakaahuatanga: IC IMAGE SENSOR 1080P 50-CSP3 I roto i te taonga: 26735 pcs</p> <p>RFQ</p>	<p>OV02718-H77A-2A Kaihanga: OmniVision Technologies Whakaahuatanga: HD CAMERA CHIP SENSOR I roto i te taonga: 15051 pcs</p> <p>RFQ</p>
<p>OV02715-A68A-PC Kaihanga: OmniVision Technologies Whakaahuatanga: SENSOR IMAGE I roto i te taonga: 17830 pcs</p> <p>RFQ</p>	<p>OV02735-H66A Kaihanga: OmniVision Technologies Whakaahuatanga: IMAGE SENSOR I roto i te taonga: 21337 pcs</p> <p>RFQ</p>

