




**BR246-1000C1-48V-030L**

Tau Wae:	BR246-1000C1-48V-030L
Kaihanga / Waitohu:	Microsemi
Whakaahuatanga hua	RELAY
Ngā Rauemi:	 BR246-1000C1-48V-030L.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waeheere Stock	4440 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o BR246-1000C1-48V-030L

TAU WAE	BR246-1000C1-48V-030L
KAIHANGA	Microsemi
WHAKAAHUATANGA	RELAY
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	4440 pcs
PEPA RARAUNGA	 BR246-1000C1-48V-030L.pdf
RAUPAPA	*
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAAHUATANGA TAIPITOPITO	Relay Coil

Ngā tūtohu e hāngai ana

Microsemi BR246-1000C1-48V-030L	BR246-1000C1-48V-030L Kaiwhiwhi	BR246-1000C1-48V-030L Kaiwhakarato
BR246-1000C1-48V-030L Utu	BR246-1000C1-48V-030L Pikitia	BR246-1000C1-48V-030L Whakaahua
BR246-1000C1-48V-030L PDF Datasheet	BR246-1000C1-48V-030L Download Datasheet	Tuhinga BR246-1000C1-48V-030L
BR246-1000C1-48V-030L Stock	Hokona BR246-1000C1-48V-030L	Hokona Microsemi BR246-1000C1-48V-030L
Microsemi BR246-1000C1-48V-030L	Microsemi Kaiwhakarato	Microsemi Kaiwhiwhi
Microsemi BR246-1000C1-48V-030L	Microsemi Analog Mixed Signal Group BR246-1000C1-48V-030L	Microsemi Analog Mixed Signal Group [MIL] BR246-1000C1-48V-030L
Microsemi Consumer Medical Product Group BR246-1000C1-48V-030L	Microsemi HI-REL [MIL] BR246-1000C1-48V-030L	Microsemi Power Management Group BR246-1000C1-48V-030L
Microsemi Power Products Group BR246-1000C1-48V-030L	Microsemi SoC BR246-1000C1-48V-030L	Microsemi Commercial Components Group BR246-1000C1-48V-030L
Microsemi Corporation BR246-1000C1-48V-030L	Microsemi Solutions Sdn Bhd. BR246-1000C1-48V-030L	

Ngā Hua e hāngai ana

 <p>BR246-1000B3-48V-037M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 4797 pcs</p> <p>RFQ</p>	 <p>BR246-1000C2-48V-033L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 2902 pcs</p> <p>RFQ</p>
 <p>BR246-1000C3-48V-036M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 2868 pcs</p> <p>RFQ</p>	 <p>BR246-1000B2-48V-034M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 6987 pcs</p> <p>RFQ</p>
 <p>BR246-1000C1-48V-030M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 5382 pcs</p> <p>RFQ</p>	 <p>BR246-1000C3-48V-036L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 3761 pcs</p> <p>RFQ</p>
 <p>BR246-1000B1-48V-031M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 4818 pcs</p> <p>RFQ</p>	 <p>BR246-1000G3-48V-038L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 3386 pcs</p> <p>RFQ</p>
 <p>BR246-1000B1-48V-031L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 3243 pcs</p> <p>RFQ</p>	 <p>BR246-1000C2-48V-033M Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 6856 pcs</p> <p>RFQ</p>
 <p>BR246-1000B3-48V-037L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 5529 pcs</p> <p>RFQ</p>	 <p>BR246-1000B2-48V-034L Kaihanga: Microsemi Whakaahuatanga: RELAY I roto i te taonga: 4395 pcs</p> <p>RFQ</p>