



Leader Tech Inc.

52-CBSA-3.0X4.75X0.5

Tau Wae:	52-CBSA-3.0X4.75X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	52 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	52-CBSA-3.0X4.75X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehe Stock	4177 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 52-CBSA-3.0X4.75X0.5

TAU WAE	52-CBSA-3.0X4.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	52 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4177 pcs
PEPA RARAUNGA	52-CBSA-3.0X4.75X0.5.pdf
WHĀNUI - WHĀNUI	3.000" (76.20mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	52-CBSA-3.0X4.75X0.4 52-CBSA-3.0X4.75X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	4.750" (120.65mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 3.000" (76.20mm) X 4.750" (120.65mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 52-CBSA-3.0X4.75X0.5	52-CBSA-3.0X4.75X0.5 Kaiwhiwhi	52-CBSA-3.0X4.75X0.5 Kaiwhakarato
52-CBSA-3.0X4.75X0.5 Utu	52-CBSA-3.0X4.75X0.5 Pikitia	52-CBSA-3.0X4.75X0.5 Whakaahua
52-CBSA-3.0X4.75X0.5 PDF Datasheet	52-CBSA-3.0X4.75X0.5 Download Datasheet	Tuhinga 52-CBSA-3.0X4.75X0.5
52-CBSA-3.0X4.75X0.5 Stock	Hokona 52-CBSA-3.0X4.75X0.5	Hokona Leader Tech Inc. 52-CBSA-3.0X4.75X0.5
Leader Tech Inc. 52-CBSA-3.0X4.75X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 52-CBSA-3.0X4.75X0.5		

Ngā Hua e hāngai ana

<p>52-CBSA-3.0X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3800 pcs</p> <p>RFQ</p>	<p>52-CBSA-3.0X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3646 pcs</p> <p>RFQ</p>
<p>52-CBSA-3.0X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4285 pcs</p> <p>RFQ</p>	<p>52-CBSA-3.0X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3528 pcs</p> <p>RFQ</p>
<p>52-CBSA-3.0X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4244 pcs</p> <p>RFQ</p>	<p>52-CBSA-3.0X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3705 pcs</p> <p>RFQ</p>
<p>52-CBSA-3.0X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3508 pcs</p> <p>RFQ</p>	<p>52-CBSA-3.0X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4537 pcs</p> <p>RFQ</p>
<p>52-CBSA-3.0X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3531 pcs</p> <p>RFQ</p>	<p>52-CBSA-3.0X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3746 pcs</p> <p>RFQ</p>
<p>52-CBSA-3.25X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4368 pcs</p> <p>RFQ</p>	<p>52-CBSA-3.0X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 52 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3515 pcs</p> <p>RFQ</p>