

BOURNS® Bourns, Inc.

PEC11L-4225F-N0015

Tau Wae: PEC11L-4225F-N0015
 Kaihanga / Waitohu: Bourns, Inc.
 Whakaahuatanga hua: ROTARY ENCODER MECHANICAL 15PPR
 Ngā Rauemi: PEC11L-4225F-N0015.pdf
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 78978 pcs stock
 Tuhiinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o PEC11L-4225F-N0015

TAU WAE	PEC11L-4225F-N0015
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	ROTARY ENCODER MECHANICAL 15PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	78978 pcs
PEPA RARAUNGA	PEC11L-4225F-N0015.pdf
TUHINGA O MUA	-
KĀHUA WHAKAMUTUNGA	PC Pin
RAUPAPA	PEC11
KO TE ROTATIONAL LIFE (CYCLES MIN)	100K
PULSES IA REVOLUTION	15
MOMO PUTANGA	Quadrature (Incremental)
WHAKATAKOTORANGA	Vertical
MOMO TAE	Panel, PCB Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MOMO KUPUTUHI	Mechanical
TUHINGA	Yes
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	6mm Dia Flatted End

Ngā tūtohu e hāngai ana

Bourns, Inc. PEC11L-4225F-N0015	PEC11L-4225F-N0015 Kaiwhiwhi	PEC11L-4225F-N0015 Kaiwhakarato
PEC11L-4225F-N0015 Utu	PEC11L-4225F-N0015 Pikitia	PEC11L-4225F-N0015 Whakaahua
PEC11L-4225F-N0015 PDF Datasheet	PEC11L-4225F-N0015 Download Datasheet	Tuhinga PEC11L-4225F-N0015
PEC11L-4225F-N0015 Stock	Hokona PEC11L-4225F-N0015	Hokona Bourns, Inc. PEC11L-4225F-N0015
Bourns, Inc. PEC11L-4225F-N0015	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. PEC11L-4225F-N0015	Bourns Inc. PEC11L-4225F-N0015	J.W. Miller / Bourns PEC11L-4225F-N0015

Ngā Hua e hāngai ana

<p>PEC11L-4220F-N0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER I roto i te taonga: 87964 pcs</p> <p>RFQ</p>	<p>PEC11R-4015F-N0018 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 18PPR I roto i te taonga: 83806 pcs</p> <p>RFQ</p>
<p>PEC11R-4015F-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 87774 pcs</p> <p>RFQ</p>	<p>PEC11R-4015F-N0024 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 24PPR I roto i te taonga: 67814 pcs</p> <p>RFQ</p>
<p>PEC11L-4225K-N0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 84990 pcs</p> <p>RFQ</p>	<p>PEC11L-4220K-S0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 68369 pcs</p> <p>RFQ</p>
<p>PEC11R-4015F-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 58213 pcs</p> <p>RFQ</p>	<p>PEC11L-4220F-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 66386 pcs</p> <p>RFQ</p>
<p>PEC11L-4220F-S0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 43373 pcs</p> <p>RFQ</p>	<p>PEC11L-4225F-S0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 41094 pcs</p> <p>RFQ</p>
<p>PEC11L-4215F-S0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 43863 pcs</p> <p>RFQ</p>	<p>PEC11L-4215K-S0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER I roto i te taonga: 85915 pcs</p> <p>RFQ</p>