



Taoglas

AP.10B.07.0050B

Tau Wae:

AP.10B.07.0050B

Kaihanga / Waitohu:

Taoglas

Whakaahuatanga hua

RF ANT 1.575GHZ CER PATCH IPEX

Ngā Rauemi:

AP.10B.07.0050B.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

5251 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o AP.10B.07.0050B

TAU WAE	AP.10B.07.0050B
KAIHANGA	Taoglas
WHAKAAHUATANGA	RF ANT 1.575GHZ CER PATCH IPEX
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	5251 pcs
PEPA RARAUNGA	AP.10B.07.0050B.pdf
VSWR	2
WHAKAMUTUNGA	Connector, IPEX MHFI (U.FL)
RAUPAPA	-
HOKI HOKI	-
PACKAGING	Tray
ĒTAHI INGOA	931-1011
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TIAKI INGOA	-
TEITEI (MAX)	0.157" (4.00mm)
HUA	-3dBic
MAHINGA RAWE	-
RANGAHAU RŌPŪ	UHF (1 GHz ~ 2 GHz)
TAUTANGA (POARI / PAE)	1.575GHz
NGĀ ĀHUATANGA	LNA
WHAKAAHUATANGA TAIPITOPITO	1.575GHz GPS Ceramic Patch RF Antenna -3dBic Connector, IPEX MHFI (U.FL) Surface Mount
NGA TONO	GPS
MOMO ANTENNA	Ceramic Patch

Ngā tūtohu e hāngai ana

Taoglas AP.10B.07.0050B	AP.10B.07.0050B Kaiwhiwhi	AP.10B.07.0050B Kaiwhakarato
AP.10B.07.0050B Utu	AP.10B.07.0050B Pikitia	AP.10B.07.0050B Whakaahua
AP.10B.07.0050B PDF Datasheet	AP.10B.07.0050B Download Datasheet	Tuhinga AP.10B.07.0050B
AP.10B.07.0050B Stock	Hokona AP.10B.07.0050B	Hokona Taoglas AP.10B.07.0050B
Taoglas AP.10B.07.0050B	Taoglas Kaiwhakarato	Taoglas Kaiwhiwhi
Taoglas AP.10B.07.0050B	Taoglas Limited AP.10B.07.0050B	

Ngā Hua e hāngai ana

<p>AP.12B.07.0046A Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH CAB I roto i te taonga: 5826 pcs</p> <p>RFQ</p>	<p>AP.10H.01 Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH SLD I roto i te taonga: 5461 pcs</p> <p>RFQ</p>
<p>AP.10C.01 Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH SLD I roto i te taonga: 4752 pcs</p> <p>RFQ</p>	<p>AP.12F.07.0045A Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH MHFI I roto i te taonga: 5847 pcs</p> <p>RFQ</p>
<p>AP.10F.07.0039B Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH CAB I roto i te taonga: 4773 pcs</p> <p>RFQ</p>	<p>AP.17A.07.0040A Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH IPEX I roto i te taonga: 6588 pcs</p> <p>RFQ</p>
<p>AP.10A.07.0050B Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH IPEX I roto i te taonga: 2797 pcs</p> <p>RFQ</p>	<p>AP.10G.01 Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH SLD I roto i te taonga: 5622 pcs</p> <p>RFQ</p>
<p>AP.17E.07.0064A Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH MHFI I roto i te taonga: 7497 pcs</p> <p>RFQ</p>	<p>AP.10E.07.0039B Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH CAB I roto i te taonga: 4835 pcs</p> <p>RFQ</p>
<p>AP.17B.07.0040A Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH IPEX I roto i te taonga: 5876 pcs</p> <p>RFQ</p>	<p>AP.10D.01 Kaihanga: Taoglas Whakaahuatanga: RF ANT 1.575GHZ CER PATCH SLD I roto i te taonga: 3189 pcs</p> <p>RFQ</p>