



Micrel / Microchip Technology

SY89873LMG-TR

Tau Wae:

SY89873LMG-TR

Kaihanga / Waitohu:

Micrel / Microchip Technology

Whakaahuatanga hua

IC CLK BUFFER 1:3 2GHZ 16MLF

Ngā Rauemi:

 SY89873LMG-TR.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Waehere Stock

19369 pcs stock

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o SY89873LMG-TR

TAU WAE	SY89873LMG-TR
KAIHANGA	Micrel / Microchip Technology
WHAKAAHUATANGA	IC CLK BUFFER 1:3 2GHZ 16MLF
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	19369 pcs
PEPA RARAUNGA	 SY89873LMG-TR.pdf
TUHINGA O MUA	2.97 V ~ 3.63 V
MOMO	Fanout Buffer (Distribution), Divider
PŪRERE PŪRERE WHAKARATO	16-MLF® (3x3)
RAUPAPA	Precision Edge®
RATONGA - WHAKAURU: WHAKAPUTA	1:3
PACKAGING	Tape & Reel (TR)
PAA / CASE	16-VFQFN Exposed Pad, 16-MLF®
WHAKAPUTA	LVDS
ĒTAHI INGOA	SY89873LMG TR SY89873LMG TR-ND SY89873LMGTR SY89873LMGTR-ND
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	CML, HSTL, LVDS, LVPECL
TAUTANGA - MAX	2GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Divider IC 1:3 2GHZ 16-VFQFN Exposed Pad, 16-MLF®
TAU WAE TUAKIRI	SY89873

Ngā tūtohu e hāngai ana

Micrel / Microchip Technology SY89873LMG-TR	SY89873LMG-TR Kaihiwhi	SY89873LMG-TR Kaiwhakarato
SY89873LMG-TR Utu	SY89873LMG-TR Pikitia	SY89873LMG-TR Whakaahua
SY89873LMG-TR PDF Datasheet	SY89873LMG-TR Download Datasheet	Tuhinga SY89873LMG-TR
SY89873LMG-TR Stock	Hokona SY89873LMG-TR	Hokona Micrel / Microchip Technology SY89873LMG-TR
Micrel / Microchip Technology SY89873LMG-TR	Micrel / Microchip Technology Kaiwhakarato	Micrel / Microchip Technology Kaihiwhi
Micrel / Microchip Technology SY89873LMG-TR	Microchip Technology SY89873LMG-TR	Roving Networks / Microchip Technology SY89873LMG-TR

Ngā Hua e hāngai ana

 <p>SY89874UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:2 2.5GHZ 16MLF I roto i te taonga: 20207 pcs</p> <p>RFQ</p>	 <p>SY89874UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:2 2.5GHZ 16MLF I roto i te taonga: 12788 pcs</p> <p>RFQ</p>
 <p>SY89872UMI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 15862 pcs</p> <p>RFQ</p>	 <p>SY89873LMI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 17253 pcs</p> <p>RFQ</p>
 <p>SY89872UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 10243 pcs</p> <p>RFQ</p>	 <p>SY89872UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 11624 pcs</p> <p>RFQ</p>
 <p>SY89871UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:2 2.5GHZ 16MLF I roto i te taonga: 23360 pcs</p> <p>RFQ</p>	 <p>SY89873LMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 16313 pcs</p> <p>RFQ</p>
 <p>SY89874AUMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:2 2.5GHZ 16QFN I roto i te taonga: 15846 pcs</p> <p>RFQ</p>	 <p>SY89873LMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 22290 pcs</p> <p>RFQ</p>
 <p>SY89872UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:3 2GHZ 16MLF I roto i te taonga: 22295 pcs</p> <p>RFQ</p>	 <p>SY89874AUMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:2 2.5GHZ 16QFN I roto i te taonga: 18655 pcs</p> <p>RFQ</p>