



TDK Corporation

DPX202690DT-4149A2

Tau Wae: DPX202690DT-4149A2
 Kaihanga / Waitohu: TDK Corporation
 Whakaahuatanga hua: RF DIPLEXER 832MHZ/2.2GHZ 0805
 Ngā Rauemi: DPX202690DT-4149A2.pdf
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 90202 pcs stock
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DPX202690DT-4149A2

TAU WAE	DPX202690DT-4149A2
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	RF DIPLEXER 832MHZ/2.2GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	90202 pcs
PEPA RARAUNGA	DPX202690DT-4149A2.pdf
RAUPAPA	DPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	12dB / 14dB
PACKAGING	Cut Tape (CT)
PAA / CASE	0805 (2012 Metric), 6 PC Pad
ĒTAHI INGOA	445-15621-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	13.00dB / 17.00dB
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	17.00dB / 20.00dB
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	704MHz ~ 960MHz / 1.71GHz ~ 2.69GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 704MHz ~ 960MHz / 1.71GHz ~ 2.69GHz 0805 (2012 Metric), 6 PC Pad

Ngā tūtohu e hāngai ana

TDK Corporation DPX202690DT-4149A2	DPX202690DT-4149A2 Kaihiwhi	DPX202690DT-4149A2 Kaiwhakarato
DPX202690DT-4149A2 Utu	DPX202690DT-4149A2 Pikitia	DPX202690DT-4149A2 Whakaahua
DPX202690DT-4149A2 PDF Datasheet	DPX202690DT-4149A2 Download Datasheet	Tuhinga DPX202690DT-4149A2
DPX202690DT-4149A2 Stock	Hokona DPX202690DT-4149A2	Hokona TDK Corporation DPX202690DT-4149A2
TDK Corporation DPX202690DT-4149A2	TDK Corporation Kaiwhakarato	TDK Corporation Kaihiwhi
TDK Corporation DPX202690DT-4149A2		

Ngā Hua e hāngai ana

<p>DPX202700DT-4035B5 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1159MHZ/2.31GHZ 0805 I roto i te taonga: 304994 pcs</p> <p>RFQ</p>	<p>DPX202690DT-4060A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0805 6 PC PAD I roto i te taonga: 106210 pcs</p> <p>RFQ</p>
<p>DPX202700DT-4062A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 829MHZ/2.3GHZ 0805 I roto i te taonga: 296631 pcs</p> <p>RFQ</p>	<p>DPX202690DT-4049A2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 832MHZ/2.2GHZ 0805 I roto i te taonga: 312457 pcs</p> <p>RFQ</p>
<p>DPX2024WD15 Kaihanga: TDK-Lambda Americas, Inc. Whakaahuatanga: DC/DC CONVERTER +/-15V 20W I roto i te taonga: 646 pcs</p> <p>RFQ</p>	<p>DPX204752DT-4028A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.4GHZ/3.965GHZ 0805 I roto i te taonga: 271737 pcs</p> <p>RFQ</p>
<p>DPX202500DT-9032A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1497MHZ/2.45GHZ 0805 I roto i te taonga: 101916 pcs</p> <p>RFQ</p>	<p>DPX202750DT-4058A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0805 6 PC PAD I roto i te taonga: 275500 pcs</p> <p>RFQ</p>
<p>DPX2024WS05 Kaihanga: TDK-Lambda Americas, Inc. Whakaahuatanga: DC/DC CONVERTER 5V 20W I roto i te taonga: 702 pcs</p> <p>RFQ</p>	<p>DPX2024WS3P3 Kaihanga: TDK-Lambda Americas, Inc. Whakaahuatanga: DC/DC CONVERTER 3.3V 20W I roto i te taonga: 728 pcs</p> <p>RFQ</p>
<p>DPX205850DT-4055A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1345M/4.125GHZ 0805 I roto i te taonga: 236414 pcs</p> <p>RFQ</p>	<p>DPX205850DT-4052B2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0805 6 PC PAD I roto i te taonga: 106367 pcs</p> <p>RFQ</p>

