



AVX Corporation

CP0402A1950ALTR

Tau Wae:

CP0402A1950ALTR

Kaihanga / Waitohu:

AVX Corporation

Whakaahuatanga hua

RF DIR COUPLER 1.9GHZ 0402

Ngā Rauemi:

CP0402A1950ALTR.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

414676 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CP0402A1950ALTR

TAU WAE	CP0402A1950ALTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.9GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	414676 pcs
PEPA RARAUNGA	CP0402A1950ALTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
ĒTAHI INGOA	CP0402A1950AL CP0402A1950AL-ND
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	1.9GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 1.9GHz 3W 0402 (1005 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

Ngā tūtohu e hāngai ana

AVX Corporation CP0402A1950ALTR	CP0402A1950ALTR Kaiwhiwhi	CP0402A1950ALTR Kaiwhakarato
CP0402A1950ALTR Utu	CP0402A1950ALTR Pikitia	CP0402A1950ALTR Whakaahua
CP0402A1950ALTR PDF Datasheet	CP0402A1950ALTR Download Datasheet	Tuhinga CP0402A1950ALTR
CP0402A1950ALTR Stock	Hokona CP0402A1950ALTR	Hokona AVX Corporation CP0402A1950ALTR
AVX Corporation CP0402A1950ALTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaiwhiwhi
AVX Corporation CP0402A1950ALTR	AVX Corporation [MIL] CP0402A1950ALTR	

Ngā Hua e hāngai ana

<p>CP0402A1950CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 486772 pcs</p> <p>RFQ</p>	<p>CP0402A1880ENTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 479821 pcs</p> <p>RFQ</p>
<p>CP0402A1950ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 392608 pcs</p> <p>RFQ</p>	<p>CP0402A1890ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0402 I roto i te taonga: 502970 pcs</p> <p>RFQ</p>
<p>CP0402A1950FLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 464652 pcs</p> <p>RFQ</p>	<p>CP0402A1880ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 415023 pcs</p> <p>RFQ</p>
<p>CP0402A1960ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.93-1.99GHZ 0402 I roto i te taonga: 433792 pcs</p> <p>RFQ</p>	<p>CP0402A1950BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 487993 pcs</p> <p>RFQ</p>
<p>CP0402A1950DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 474253 pcs</p> <p>RFQ</p>	<p>CP0402A1880DNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 435221 pcs</p> <p>RFQ</p>
<p>CP0402A1890ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0402 I roto i te taonga: 459521 pcs</p> <p>RFQ</p>	<p>CP0402A1880DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 459126 pcs</p> <p>RFQ</p>

