



22-CBSA-1.5X1.75X0.2

Tau Wae:	22-CBSA-1.5X1.75X0.2
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	22 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	22-CBSA-1.5X1.75X0.2.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	5867 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 22-CBSA-1.5X1.75X0.2

TAU WAE	22-CBSA-1.5X1.75X0.2
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	22 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	5867 pcs
PEPA RARAUNGA	22-CBSA-1.5X1.75X0.2.pdf
WHĀNUI - WHĀNUI	1.500" (38.10mm)
TUHINGA O MUA	Non-Vented
MOMO	Shield, 2-Piece
RAUPAPA	20-CBS
MOMO TAE	Surface Mount, Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	1.750" (44.45mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.200" (5.08mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.500" (38.10mm) X 1.750" (44.45mm) Non-Vented Surface Mount, Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 22-CBSA-1.5X1.75X0.2	22-CBSA-1.5X1.75X0.2 Kaihiwhi	22-CBSA-1.5X1.75X0.2 Kaiwhakarato
22-CBSA-1.5X1.75X0.2 Utu	22-CBSA-1.5X1.75X0.2 Pikitia	22-CBSA-1.5X1.75X0.2 Whakaahua
22-CBSA-1.5X1.75X0.2 PDF Datasheet	22-CBSA-1.5X1.75X0.2 Download Datasheet	Tuhinga 22-CBSA-1.5X1.75X0.2
22-CBSA-1.5X1.75X0.2 Stock	Hokona 22-CBSA-1.5X1.75X0.2	Hokona Leader Tech Inc. 22-CBSA-1.5X1.75X0.2
Leader Tech Inc. 22-CBSA-1.5X1.75X0.2	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaihiwhi
Leader Tech Inc. 22-CBSA-1.5X1.75X0.2		

Ngā Hua e hāngai ana

<p>22-CBSA-1.5X2.0X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5473 pcs</p> <p>RFQ</p>	<p>22-CBSA-1.5X3.0X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4998 pcs</p> <p>RFQ</p>
<p>22-CBSA-1.25X6.0X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4697 pcs</p> <p>RFQ</p>	<p>22-CBSA-1.5X2.75X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4948 pcs</p> <p>RFQ</p>
<p>22-CBSA-1.25X5.5X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3843 pcs</p> <p>RFQ</p>	<p>22-CBSA-1.25X5.0X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4245 pcs</p> <p>RFQ</p>
<p>22-CBSA-1.5X2.25X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5242 pcs</p> <p>RFQ</p>	<p>22-CBSA-1.5X3.25X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5661 pcs</p> <p>RFQ</p>
<p>22-CBSA-1.25X5.25X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4078 pcs</p> <p>RFQ</p>	<p>22-CBSA-1.25X5.75X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3757 pcs</p> <p>RFQ</p>
<p>22-CBSA-1.5X2.5X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5786 pcs</p> <p>RFQ</p>	<p>22-CBSA-1.5X1.5X0.2 Kaihanga: Leader Tech Inc. Whakaahuatanga: 22 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5795 pcs</p> <p>RFQ</p>