



Leader Tech Inc.

10-CBSA-0.75X1.0X0.13

Tau Wae:	10-CBSA-0.75X1.0X0.13
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	10 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	10-CBSA-0.75X1.0X0.13.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	4885 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 10-CBSA-0.75X1.0X0.13

TAU WAE	10-CBSA-0.75X1.0X0.13
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	10 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4885 pcs
PEPA RARAUNGA	10-CBSA-0.75X1.0X0.13.pdf
WHĀNUI - WHĀNUI	0.750" (19.05mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	10-CBS
PACKAGING	Bulk
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	1.000" (25.40mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.130" (3.30mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 0.750" (19.05mm) X 1.000" (25.40mm) Vent Holes in Pattern Surface Mount

Ngā tūtohu e hāngai ana

Leader Tech Inc. 10-CBSA-0.75X1.0X0.13	10-CBSA-0.75X1.0X0.13 Kaiwhiwhi	10-CBSA-0.75X1.0X0.13 Kaiwhakarato
10-CBSA-0.75X1.0X0.13 Utu	10-CBSA-0.75X1.0X0.13 Pikitia	10-CBSA-0.75X1.0X0.13 Whakaahua
10-CBSA-0.75X1.0X0.13 PDF Datasheet	10-CBSA-0.75X1.0X0.13 Download Datasheet	Tuhinga 10-CBSA-0.75X1.0X0.13
10-CBSA-0.75X1.0X0.13 Stock	Hokona 10-CBSA-0.75X1.0X0.13	Hokona Leader Tech Inc. 10-CBSA-0.75X1.0X0.13
Leader Tech Inc. 10-CBSA-0.75X1.0X0.13	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 10-CBSA-0.75X1.0X0.13		

Ngā Hua e hāngai ana

<p>10-CBSA-0.75X2.5X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5424 pcs</p> <p>RFQ</p>	<p>10-CBSA-0.75X0.75X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5254 pcs</p> <p>RFQ</p>
<p>10-CBSA-0.5X5.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4707 pcs</p> <p>RFQ</p>	<p>10-CBSA-0.75X1.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 6150 pcs</p> <p>RFQ</p>
<p>10-CBSA-0.5X5.5X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4200 pcs</p> <p>RFQ</p>	<p>10-CBSA-0.75X2.25X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5306 pcs</p> <p>RFQ</p>
<p>10-CBSA-0.75X2.0X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5914 pcs</p> <p>RFQ</p>	<p>10-CBSA-0.5X6.0X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3905 pcs</p> <p>RFQ</p>
<p>10-CBSA-0.75X1.75X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5337 pcs</p> <p>RFQ</p>	<p>10-CBSA-0.5X5.75X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3857 pcs</p> <p>RFQ</p>
<p>10-CBSA-0.75X1.5X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5979 pcs</p> <p>RFQ</p>	<p>10-CBSA-0.5X5.0X0.13 Kaihanga: Leader Tech Inc. Whakaahuatanga: 10 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4538 pcs</p> <p>RFQ</p>