



Renesas Electronics America

R5F211A1SP#U0

Tau Wae:

R5F211A1SP#U0

Kaihanga / Waitohu:

Renesas Electronics America

Whakaahuatanga hua

IC MCU 16BIT 4KB FLASH 20LSSOP

Ngā Rauemi:

- 1.R5F211A1SP#U0.pdf
- 2.R5F211A1SP#U0.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehe Stock

27828 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o R5F211A1SP#U0

TAU WAE	R5F211A1SP#U0
KAIHANGA	Renesas Electronics America
WHAKAAHUATANGA	IC MCU 16BIT 4KB FLASH 20LSSOP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	27828 pcs
PEPA RARAUNGA	1.R5F211A1SP#U0.pdf 2.R5F211A1SP#U0.pdf
NGAOHIHI - WHAKAAETANGA (VCC / VDD)	2.7 V ~ 5.5 V
PŪRERE PŪRERE WHAKARATO	20-LSSOP
TERE	20MHz
RAUPAPA	R8C/1x/1A
RAHI RAM	384 x 8
MOMO MOMO RATONGA	FLASH
RAHI MOTU RATONGA	4KB (4K x 8)
NGA PAPA HANGA REO	LED, POR, Voltage Detect, WDT
PACKAGING	Tube
PAA / CASE	20-LSSOP (0.173", 4.40mm Width)
ĒTAHI INGOA	R5F211A1SP#V0 R5F211A1SP#V0-ND R5F211A1SP#U0
OSCILLATOR MOMO	Internal
TAE MAHI	-20°C ~ 85°C (TA)
TAU O I / O	13
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAE EEPROM	-
WHAKAAHUATANGA TAIPITOPITO	R8C R8C/1x/1A Microcontroller IC 16-Bit 20MHz 4KB (4K x 8) FLASH 20-LSSOP
RARAUNGA RARAUNGA	A/D 4x10b
NUI RAHI	16-Bit
TE TUKATUKA CORE	R8C
HONONGA	I ² C, SIO, SSSU, UART/USART
TAU WAE TUAKIRI	R5F211A

Ngā tūtohu e hāngai ana

Renesas Electronics America R5F211A1SP#U0	R5F211A1SP#U0 Kaiwhiwhi	R5F211A1SP#U0 Kaiwhakarato
R5F211A1SP#U0 Utu	R5F211A1SP#U0 Pikitia	R5F211A1SP#U0 Whakaahua
R5F211A1SP#U0 PDF Datasheet	R5F211A1SP#U0 Download Datasheet	Tuhinga R5F211A1SP#U0
R5F211A1SP#U0 Stock	Hokona R5F211A1SP#U0	Hokona Renesas Electronics America R5F211A1SP#U0
Renesas Electronics America R5F211A1SP#U0	Renesas Electronics America Kaiwhakarato	Renesas Electronics America Kaiwhiwhi
Renesas Electronics America R5F211A1SP#U0	Renesas Technology Corp R5F211A1SP#U0	Renesas R5F211A1SP#U0

Ngā Hua e hāngai ana

<p>R5F21194DD#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 16KB FLASH 20SDIP I roto i te taonga: 14516 pcs</p> <p>RFQ</p>	<p>R5F211A1DSP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 4KB FLASH 20LSSOP I roto i te taonga: 4498 pcs</p> <p>RFQ</p>
<p>R5F211A2SP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 8KB FLASH 20LSSOP I roto i te taonga: 21988 pcs</p> <p>RFQ</p>	<p>R5F211A2DSP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 8KB FLASH 20LSSOP I roto i te taonga: 38986 pcs</p> <p>RFQ</p>
<p>R5F211A3SP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 12KB FLASH 20LSSOP I roto i te taonga: 31118 pcs</p> <p>RFQ</p>	<p>R5F21194NP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 16KB FLASH 28HWQFN I roto i te taonga: 21009 pcs</p> <p>RFQ</p>
<p>R5F211A3DSP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 12KB FLASH 20LSSOP I roto i te taonga: 21612 pcs</p> <p>RFQ</p>	<p>R5F21194SP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 16KB FLASH 20LSSOP I roto i te taonga: 5509 pcs</p> <p>RFQ</p>
<p>R5F21194DSP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 16KB FLASH 20LSSOP I roto i te taonga: 29189 pcs</p> <p>RFQ</p>	<p>R5F21193SP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 12KB FLASH 20LSSOP I roto i te taonga: 20295 pcs</p> <p>RFQ</p>
<p>R5F211A2NP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 8KB FLASH 28HWQFN I roto i te taonga: 31241 pcs</p> <p>RFQ</p>	<p>R5F211A4DSP#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 16KB FLASH 20LSSOP I roto i te taonga: 29247 pcs</p> <p>RFQ</p>