

Aeroflex (MACOM Technology Solutions)

Solutions

MACP-011033

Tau Wae:	MACP-011033
Kaihanga / Waitohu:	Aeroflex (MACOM Technology Solutions)
Whakaahuatanga hua:	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
Ngā Rauemi:	MACP-011033.pdf
RoHS Tūnga:	Whakahaerehia te kore utu / RoHS
Waehere Stock:	34032 pcs stock
Tuhinga mai i:	Hong Kong
Te Ara Tuhi:	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o MACP-011033

TAU WAE	MACP-011033
KAIHANGA	Aeroflex (MACOM Technology Solutions)
WHAKAAHUATANGA	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	34032 pcs
PEPA RARAUNGA	MACP-011033.pdf
PŪRERE PŪRERE WHAKARATO	6-SMD
RAUPAPA	-
HOKI HOKI	-18dB
MANA - MAX	-
PACKAGING	Cut Tape (CT)
PAA / CASE	6-SMD
ĒTAHI INGOA	1465-1806-1
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAMOTU	18dB
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	5MHz ~ 1.2GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler General Purpose 5MHz ~ 1.2GHz 8dB 6-SMD
HONONGA TAE	8dB
HE MOMO HOAHOA	Standard
NGA TONO	General Purpose

Ngā tūtohu e hāngai ana

Aeroflex (MACOM Technology Solutions) MACP-011033	MACP-011033 Kaiwhiwhi	MACP-011033 Kaiwhakarato
MACP-011033 Utu	MACP-011033 Pikitia	MACP-011033 Whakaahua
MACP-011033 PDF Datasheet	MACP-011033 Download Datasheet	Tuhinga MACP-011033
MACP-011033 Stock	Hokona MACP-011033	Hokona Aeroflex (MACOM Technology Solutions) MACP-011033
Aeroflex (MACOM Technology Solutions) MACP-011033	Aeroflex (MACOM Technology Solutions) Kaiwhakarato	Aeroflex (MACOM Technology Solutions) Kaiwhiwhi
Aeroflex (MACOM Technology Solutions) MACP-011033	Aeroflex Circuit Technology MACP-011033	Aeroflex MACP-011033
Aeroflex (MACOM Technology Solutions) MACP-011033	Aeroflex Metelics, Division of MACOM MACP-011033	M/A-Com Technology Solutions MACP-011033
Metelics (MACOM Technology Solutions) MACP-011033	MACOM Technology Solutions MACP-011033	

Ngā Hua e hāngai ana

<p>MACP-011015 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD I roto i te taonga: 24969 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>	<p>MACP-010563-TR1000 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 10GHZ-30GHZ 6TDFN I roto i te taonga: 4446 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>
<p>MACP-011032 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 33983 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>	<p>MACP-011013 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD I roto i te taonga: 75305 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>
<p>MACP-011010 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 69745 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>	<p>MACP-011034 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 34659 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>
<p>MACP-011035 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 31816 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>	<p>MACP-010563-001SMB Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: EVAL BOARD FOR MACP-010563-TR1000 I roto i te taonga: 4608 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>
<p>MACP-011038 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 5028 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>	<p>MACP-011014 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD I roto i te taonga: 34558 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>
<p>MACPCT0030 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 27402 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>	<p>MACP-011036 Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 4034 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 5px; font-weight: bold;">RFQ</p>