



Grayhill, Inc.

70RCK4R

Tau Wae:

70RCK4R

Kaihanga / Waitohu:

Grayhill, Inc.

Whakaahuatanga hua

I/O MODULE RACK 4 CHANNEL

Ngā Rauemi:

 70RCK4R.pdf

RoHS Tūnga

 Kei roto nga rangatira / RoHS kaore i te ture

Waeheere Stock


2877 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi


DHL/Fedex/TNT/UPS/EMS



Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

[TONO MO TE WHAKAHUA](#)













Ngā whakaaturanga o 70RCK4R

TAU WAE	70RCK4R
KAIHANGA	Grayhill, Inc.
WHAKAAHUATANGA	I/O MODULE RACK 4 CHANNEL
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	2877 pcs
PEPA RARAUNGA	 70RCK4R.pdf
KĀHUA	Standard
RAUPAPA	System 50
ĒTAHI INGOA	GH3035
TE MAHA O NGA POUAKA	4
MOMO TAE	Standoffs
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAAHUATANGA TAIPITOPITO	I/O Module Rack 4 Channel
MOMO HONONGA	Screw Terminal Blocks

Ngā tūtohu e hāngai ana

Grayhill, Inc. 70RCK4R	70RCK4R Kaiwhiwhi	70RCK4R Kaiwhakarato
70RCK4R Utu	70RCK4R Pikitia	70RCK4R Whakaahua
70RCK4R PDF Datasheet	70RCK4R Download Datasheet	Tuhinga 70RCK4R
70RCK4R Stock	Hokona 70RCK4R	Hokona Grayhill, Inc. 70RCK4R
Grayhill, Inc. 70RCK4R	Grayhill, Inc. Kaiwhakarato	Grayhill, Inc. Kaiwhiwhi
Grayhill, Inc. 70RCK4R	Grayhill Inc. 70RCK4R	

Ngā Hua e hāngai ana

 <p>70RCK8 Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 8 CHANNEL I roto i te taonga: 1652 pcs</p> <p>RFQ</p>	 <p>70RX30720QDLC12.5X40 Kaihanga: Rubycon Whakaahuatanga: CAP ALUM RAD I roto i te taonga: 47929 pcs</p> <p>RFQ</p>
 <p>70RCK24 Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 24 CHANNEL I roto i te taonga: 675 pcs</p> <p>RFQ</p>	 <p>70RCK16 Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 16 CHANNEL I roto i te taonga: 932 pcs</p> <p>RFQ</p>
 <p>70RCK16-HL Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 16 CHANNEL I roto i te taonga: 808 pcs</p> <p>RFQ</p>	 <p>70RCK8-HS Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 8 CHANNEL I roto i te taonga: 5095 pcs</p> <p>RFQ</p>
 <p>70RCK16-HS Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 16 CHANNEL I roto i te taonga: 6109 pcs</p> <p>RFQ</p>	 <p>70RCK24-HL Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 24 CHANNEL I roto i te taonga: 3390 pcs</p> <p>RFQ</p>
 <p>70RCK4 Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 4 CHANNEL I roto i te taonga: 2888 pcs</p> <p>RFQ</p>	 <p>70RCK32-HL Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 32 CHANNEL I roto i te taonga: 4809 pcs</p> <p>RFQ</p>
 <p>70RCK24-HS Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 24 CHANNEL I roto i te taonga: 553 pcs</p> <p>RFQ</p>	 <p>70RCK8-HL Kaihanga: Grayhill, Inc. Whakaahuatanga: I/O MODULE RACK 8 CHANNEL I roto i te taonga: 1221 pcs</p> <p>RFQ</p>

Copyright © 2020 Kaitoha Kaitoha o nga waahanga hiko

Ī-mēra: Info@infinity-electronic.com

Wāhi noho: 17F, Gaylord Hangarau Hokohoko, 114-118 Lockhart Road, Wan Chai, Hong Kong

