




2450DP15A5512E

Tau Wae:	2450DP15A5512E
Kaihanga / Waitohu:	Johanson Technology
Whakaahuatanga hua	RF DIPLEXER 2.45GHZ/5.51GHZ 0805
Ngā Rauemi:	 2450DP15A5512E.pdf
RoHS Tūnga	 Whakahaerehia te kore utu / RoHS
Waehere Stock	273914 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o 2450DP15A5512E

TAU WAE	2450DP15A5512E
KAIHANGA	Johanson Technology
WHAKAAHUATANGA	RF DIPLEXER 2.45GHZ/5.51GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	273914 pcs
PEPA RARAUNGA	 2450DP15A5512E.pdf
RAUPAPA	-
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	9.5dB / 9.5dB
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
ĒTAHI INGOA	2450DP15A5512 2450DP15A5512-ND 2450DP15A5512E-ND 712-1601-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	20.00dB / 0.70dB
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	15.00dB / 0.90dB
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	2.4GHz ~ 2.5GHz / 5.15GHz ~ 5.87GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 2.4GHz ~ 2.5GHz / 5.15GHz ~ 5.87GHz 0805 (2012 Metric)

Ngā tūtohu e hāngai ana

Johanson Technology 2450DP15A5512E	2450DP15A5512E Kaiwhiwhi	2450DP15A5512E Kaiwhakarato
2450DP15A5512E Utu	2450DP15A5512E Pikitia	2450DP15A5512E Whakaahua
2450DP15A5512E PDF Datasheet	2450DP15A5512E Download Datasheet	Tuhinga 2450DP15A5512E
2450DP15A5512E Stock	Hokona 2450DP15A5512E	Hokona Johanson Technology 2450DP15A5512E
Johanson Technology 2450DP15A5512E	Johanson Technology Kaiwhakarato	Johanson Technology Kaiwhiwhi
Johanson Technology 2450DP15A5512E	Johanson 2450DP15A5512E	Johanson Technology Inc. 2450DP15A5512E

Ngā Hua e hāngai ana

 <p>2450CP05A5400T Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 0202 4 LEAD I roto i te taonga: 180076 pcs</p> <p>RFQ</p>	 <p>2450DP15H5400E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 I roto i te taonga: 4596 pcs</p> <p>RFQ</p>
 <p>2450DP15D5400E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 I roto i te taonga: 331084 pcs</p> <p>RFQ</p>	 <p>2450DM41A5400 Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER MODULE I roto i te taonga: 6443 pcs</p> <p>RFQ</p>
 <p>2450DP15F5400E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 I roto i te taonga: 3520 pcs</p> <p>RFQ</p>	 <p>2450CMG86980002 Kaihanga: Honeywell Sensing and Productivity Solutions Whakaahuatanga: MANUAL RESET THERMOSTAT I roto i te taonga: 5913 pcs</p> <p>RFQ</p>
 <p>2450DP15E5400E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.4GHZ 1206 I roto i te taonga: 237478 pcs</p> <p>RFQ</p>	 <p>2450DM40A1575E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 1.575GHZ/2.45GHZ I roto i te taonga: 51325 pcs</p> <p>RFQ</p>
 <p>2450DP15B5512E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.51GHZ 0805 I roto i te taonga: 6736 pcs</p> <p>RFQ</p>	 <p>2450CMN80821029 Kaihanga: Honeywell Sensing and Productivity Solutions Whakaahuatanga: MANUAL RESET THERMOSTAT I roto i te taonga: 6610 pcs</p> <p>RFQ</p>
 <p>2450DP15G5400E Kaihanga: Johanson Technology Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 I roto i te taonga: 5602 pcs</p> <p>RFQ</p>	 <p>2450CMG82090129 Kaihanga: Honeywell Sensing and Productivity Solutions Whakaahuatanga: MANUAL RESET THERMOSTAT I roto i te taonga: 5789 pcs</p> <p>RFQ</p>