



ADI (Analog Devices, Inc.)

## ADM1060ARUCS0605

Tau Wae:	ADM1060ARUCS0605
Kaihanga / Waitohu:	ADI (Analog Devices, Inc.)
Whakaahuatanga hua	IC SUPERVISOR/SEQUENCER
Ngā Rauemi:	
RoHS Tūnga	Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	5585 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o ADM1060ARUCS0605

TAU WAE	ADM1060ARUCS0605
KAIHANGA	ADI (Analog Devices, Inc.)
WHAKAAHUATANGA	IC SUPERVISOR/SEQUENCER
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	5585 pcs
PEPA RARAUNGA	
RAUPAPA	*
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAAHUATANGA TAIPITOPITO	Supervisor Channel
TAU WAE TUAKIRI	ADM1060

### Ngā tūtohu e hāngai ana

ADI (Analog Devices, Inc.) ADM1060ARUCS0605	ADM1060ARUCS0605 Kaiwhiwhi	ADM1060ARUCS0605 Kaiwhakarato
ADM1060ARUCS0605 Utu	ADM1060ARUCS0605 Pikitia	ADM1060ARUCS0605 Whakaahua
ADM1060ARUCS0605 PDF Datasheet	ADM1060ARUCS0605 Download Datasheet	Tuhinga ADM1060ARUCS0605
ADM1060ARUCS0605 Stock	Hokona ADM1060ARUCS0605	Hokona ADI (Analog Devices, Inc.) ADM1060ARUCS0605
ADI (Analog Devices, Inc.) ADM1060ARUCS0605	ADI (Analog Devices, Inc.) Kaiwhakarato	ADI (Analog Devices, Inc.) Kaiwhiwhi
ADI (Analog Devices, Inc.) ADM1060ARUCS0605	AD ADM1060ARUCS0605	ADI (Analog Devices, Inc.) ADM1060ARUCS0605
Analog Devices Inc. ADM1060ARUCS0605	Analog Devices, Inc. ADM1060ARUCS0605	

### Ngā Hua e hāngai ana

<p><b>ADM1060ARUCS0603R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 4326 pcs</p> <p><b>RFQ</b></p>	<p><b>ADM1060ARUCS0704R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 5697 pcs</p> <p><b>RFQ</b></p>
<p><b>ADM1060ARUCS0701R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 3851 pcs</p> <p><b>RFQ</b></p>	<p><b>ADM1060ARUCS0703R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 4330 pcs</p> <p><b>RFQ</b></p>
<p><b>ADM1060ARUCS0702R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 3180 pcs</p> <p><b>RFQ</b></p>	<p><b>ADM1060ARUCS0605R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 6587 pcs</p> <p><b>RFQ</b></p>
<p><b>ADM1060ARUCS0704</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 5798 pcs</p> <p><b>RFQ</b></p>	<p><b>ADM1060ARUCS0601R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 3828 pcs</p> <p><b>RFQ</b></p>
<p><b>ADM1060ARUCS0602R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 3294 pcs</p> <p><b>RFQ</b></p>	<p><b>ADM1060ARUCS0403R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 6464 pcs</p> <p><b>RFQ</b></p>
<p><b>ADM1060ARUCS0604R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 4638 pcs</p> <p><b>RFQ</b></p>	<p><b>ADM1060ARUCS0501R7</b> Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC SUPERVISOR/SEQUENCER I roto i te taonga: 6628 pcs</p> <p><b>RFQ</b></p>

