

N/A

DGS35-1LN01024

Tau Wae:	DGS35-1LN01024
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 1024PPR
Ngā Rauemi:	
Waehere Stock	160 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DGS35-1LN01024

TAU WAE	DGS35-1LN01024
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 1024PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	160 pcs
PEPA RARAUNGA	
TUHINGA O MUA	4.5 V ~ 5.5 V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	1024
MOMO PUTANGA	-
ĒTAHI INGOA	1067136
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

DGS35-1LN01024	DGS35-1LN01024 Kaiwhiwhi	DGS35-1LN01024 Kaiwhakarato
DGS35-1LN01024 Utu	DGS35-1LN01024 Pikitia	DGS35-1LN01024 Whakaahua
DGS35-1LN01024 PDF Datasheet	DGS35-1LN01024 Download Datasheet	Tuhinga DGS35-1LN01024
DGS35-1LN01024 Stock	Hokona DGS35-1LN01024	Hokona DGS35-1LN01024
DGS35-1LN01024	Kaiwhakarato	Kaiwhiwhi

Ngā Hua e hāngai ana

	<p>DGS35-1L202048</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 207 pcs</p> <p>RFQ</p>		<p>DGS35-2HN01024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 179 pcs</p> <p>RFQ</p>
	<p>DGS35-1LN05000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: 207 pcs</p> <p>RFQ</p>		<p>DGS35-2KK02048</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 193 pcs</p> <p>RFQ</p>
	<p>DGS35-2H401024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 199 pcs</p> <p>RFQ</p>		<p>DGS35-2KK16384</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 173 pcs</p> <p>RFQ</p>
	<p>DGS35-1LN04096</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 181 pcs</p> <p>RFQ</p>		<p>DGS35-1L202500</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 176 pcs</p> <p>RFQ</p>
	<p>DGS35-1L402500</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 199 pcs</p> <p>RFQ</p>		<p>DGS35-1LM01024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 184 pcs</p> <p>RFQ</p>
	<p>DGS35-1L204096</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 218 pcs</p> <p>RFQ</p>		<p>DGS35-1LN00120</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENTAL 120PPR I roto i te taonga: 167 pcs</p> <p>RFQ</p>