



0896FB15A0100E

Tau Wae:	0896FB15A0100E
Kaihanga / Waitohu:	Johanson Technology
Whakaahuatanga hua	BALUN 863MHZ-928MHZ 50/100 0805
Ngā Rauemi:	0896FB15A0100E.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	84738 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 0896FB15A0100E

TAU WAE	0896FB15A0100E
KAIHANGA	Johanson Technology
WHAKAAHUATANGA	BALUN 863MHZ-928MHZ 50/100 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	84738 pcs
PEPA RARAUNGA	0896FB15A0100E.pdf
RAUPAPA	-
HOKI HOKI (MIN)	11.7dB
RAWEHANGA PUTANGA	180° ±15°
PACKAGING	Cut Tape (CT)
PAA / CASE	0805 (2012 Metric)
ĒTAHI INGOA	712-1473-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.5dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	863MHz ~ 928MHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 863MHz ~ 928MHz 50 / 100 Ohm 0805 (2012 Metric)

Ngā tūtohu e hāngai ana

Johanson Technology 0896FB15A0100E	0896FB15A0100E Kaihiwhi	0896FB15A0100E Kaiwhakarato
0896FB15A0100E Utu	0896FB15A0100E Pikitia	0896FB15A0100E Whakaahua
0896FB15A0100E PDF Datasheet	0896FB15A0100E Download Datasheet	Tuhinga 0896FB15A0100E
0896FB15A0100E Stock	Hokona 0896FB15A0100E	Hokona Johanson Technology 0896FB15A0100E
Johanson Technology 0896FB15A0100E	Johanson Technology Kaiwhakarato	Johanson Technology Kaihiwhi
Johanson Technology 0896FB15A0100E	Johanson 0896FB15A0100E	Johanson Technology Inc. 0896FB15A0100E

Ngā Hua e hāngai ana

<p>0896100104 Kaihanga: Affinity Medical Technologies - a Molex company Whakaahuatanga: CONN LOCKWASHER I roto i te taonga: 212086 pcs</p> <p>RFQ</p>	<p>0897005.N Kaihanga: Hamlin / Littelfuse Whakaahuatanga: FUSE AUTO 5A 58VDC BLADE MINI I roto i te taonga: 7099 pcs</p> <p>RFQ</p>
<p>0896740611 Kaihanga: Affinity Medical Technologies - a Molex company Whakaahuatanga: GASKET,SMA J,BULKHEAD/RG 405 SEM I roto i te taonga: 3327 pcs</p> <p>RFQ</p>	<p>0896BM15A0032E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 863MHZ-928MHZ 0805 6 LEAD I roto i te taonga: 375922 pcs</p> <p>RFQ</p>
<p>0896BM15E0025E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 863MHZ-928MHZ 50/50 0805 I roto i te taonga: 368392 pcs</p> <p>RFQ</p>	<p>0896BM15A0001E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 863MHZ-928MHZ 0805 I roto i te taonga: 99853 pcs</p> <p>RFQ</p>
<p>0897015.N Kaihanga: Hamlin / Littelfuse Whakaahuatanga: FUSE AUTO 15A 58VDC BLADE MINI I roto i te taonga: 3745 pcs</p> <p>RFQ</p>	<p>0897003.N Kaihanga: Hamlin / Littelfuse Whakaahuatanga: FUSE AUTO 3A 58VDC BLADE MINI I roto i te taonga: 3091 pcs</p> <p>RFQ</p>
<p>0897002.N Kaihanga: Hamlin / Littelfuse Whakaahuatanga: FUSE AUTO 2A 58VDC BLADE MINI I roto i te taonga: 5507 pcs</p> <p>RFQ</p>	<p>0897004.N Kaihanga: Hamlin / Littelfuse Whakaahuatanga: FUSE AUTO 4A 58VDC BLADE MINI I roto i te taonga: 3036 pcs</p> <p>RFQ</p>
<p>08966 Kaihanga: 3M Whakaahuatanga: 3M NO CLEANUP REPLACEMENT NO I roto i te taonga: 2694 pcs</p> <p>RFQ</p>	<p>0897010.N Kaihanga: Hamlin / Littelfuse Whakaahuatanga: FUSE AUTO 10A 58VDC BLADE MINI I roto i te taonga: 5991 pcs</p> <p>RFQ</p>