



MaxBotix Inc.

## MB7563-100

Tau Wae:

MB7563-100

Kaihanga / Waitohu:

MaxBotix Inc.

Whakaahuatanga hua

ULTRASONIC SENSOR SCXL-MAXSONAR

Ngā Rauemi:

MB7563-100.pdf

RoHS Tūnga

RoHS Compliant

Waehere Stock

568 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o MB7563-100

TAU WAE	MB7563-100
KAIHANGA	MaxBotix Inc.
WHAKAAHUATANGA	ULTRASONIC SENSOR SCXL-MAXSONAR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	RoHS Compliant
HE RAHINGA KEI TE WĀTEA	568 pcs
PEPA RARAUNGA	MB7563-100.pdf
PUTANGA - KUA TOHUA	2.5 V ~ 5.5 V
RAUPAPA	SCXL-MaxSonar-WR
ROHS TŪNGA	RoHS Compliant
PACKAGING	Bulk
ĒTAHI INGOA	1863-1089
TAE MAHI	-40°C ~ 65°C (TA)
RAUTANGA	42kHz
WHAKAAHUATANGA TAIPITOPITO	Ultrasonic Sensor 42kHz
TE PEE MAAMA	17°

### Ngā tūtohu e hāngai ana

MaxBotix Inc. MB7563-100	MB7563-100 Kaiwhiwhi	MB7563-100 Kaiwhakarato
MB7563-100 Utu	MB7563-100 Pikitia	MB7563-100 Whakaahua
MB7563-100 PDF Datasheet	MB7563-100 Download Datasheet	Tuhinga MB7563-100
MB7563-100 Stock	Hokona MB7563-100	Hokona MaxBotix Inc. MB7563-100
MaxBotix Inc. MB7563-100	MaxBotix Inc. Kaiwhakarato	MaxBotix Inc. Kaiwhiwhi
MaxBotix Inc. MB7563-100		

### Ngā Hua e hāngai ana

<p><b>MB7563-111</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 351 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7560-730</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 442 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7563-120</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 414 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7560-720</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 487 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7563-101</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 408 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7563-130</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 392 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7560-721</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 313 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7560-711</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 342 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7560-731</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 351 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7563-121</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 374 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7560-710</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 474 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7563-110</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR SCXL-MAXSONAR I roto i te taonga: 424 pcs</p> <p><b>RFQ</b></p>