



BOURNS®

Bourns, Inc.


AMS22S5A1BHAF321

Tau Wae:	AMS22S5A1BHAF321
Kaihanga / Waitohu:	Bourns, Inc.
Whakaahuatanga hua	SENSOR ROTARY 210DEG SOLDER LUG
Ngā Rauemi:	 AMS22S5A1BHAF321.pdf
RoHS Tūnga	 Whakahaerehia te kore utu / RoHS
Waeheere Stock	2256 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o AMS22S5A1BHAF321

TAU WAE	AMS22S5A1BHAF321
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	SENSOR ROTARY 210DEG SOLDER LUG
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	2256 pcs
PEPA RARAUNGA	 AMS22S5A1BHAF321.pdf
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Solder Lug
HANGARAU	Hall Effect
PŪRERE PŪRERE WHAKARATO	-
RAUPAPA	AMS22S
MAHINGA WHAKATERE - HANGARAU, HANGARAU	10° ~ 210°, Continuous
TE TANGATA TANGATA	-
PACKAGING	Bulk
PAA / CASE	Module, Flatted Shaft
WAITOHU WHAKAPUTA	Clockwise Increase
WHAKAPUTA	Analog Voltage
TAE MAHI	-40°C ~ 125°C
MOMO TAE	Panel Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TUHINGA	±0.5%
RAINA RAINA	-
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MO TE INE	Rotary Position
WHAKAAHUATANGA TAIPITOPITO	Hall Effect Sensor Rotary Position Flatted Shaft Solder Lug
MOMO KAIHOKO	Flatted Shaft

Ngā tūtohu e hāngai ana

Bourns, Inc. AMS22S5A1BHAF321	AMS22S5A1BHAF321 Kaiwhiwhi	AMS22S5A1BHAF321 Kaiwhakarato
AMS22S5A1BHAF321 Utu	AMS22S5A1BHAF321 Pikitia	AMS22S5A1BHAF321 Whakaahua
AMS22S5A1BHAF321 PDF Datasheet	AMS22S5A1BHAF321 Download Datasheet	Tuhinga AMS22S5A1BHAF321
AMS22S5A1BHAF321 Stock	Hokona AMS22S5A1BHAF321	Hokona Bourns, Inc. AMS22S5A1BHAF321
Bourns, Inc. AMS22S5A1BHAF321	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. AMS22S5A1BHAF321	Bourns Inc. AMS22S5A1BHAF321	J.W. Miller / Bourns AMS22S5A1BHAF321

Ngā Hua e hāngai ana

 <p>AMS22S5A1BHAF319 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 190DEG SOLDER LUG I roto i te taonga: 1829 pcs</p> <p>RFQ</p>	 <p>AMS22S5A1BHAF326 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 260DEG SOLDER LUG I roto i te taonga: 1865 pcs</p> <p>RFQ</p>
 <p>AMS22S5A1BHAF322 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 220DEG SOLDER LUG I roto i te taonga: 1764 pcs</p> <p>RFQ</p>	 <p>AMS22S5A1BHAF315 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 150DEG SOLDER LUG I roto i te taonga: 2004 pcs</p> <p>RFQ</p>
 <p>AMS22S5A1BHAF324 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 240DEG SOLDER LUG I roto i te taonga: 2261 pcs</p> <p>RFQ</p>	 <p>AMS22S5A1BHAF316 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 160DEG SOLDER LUG I roto i te taonga: 1714 pcs</p> <p>RFQ</p>
 <p>AMS22S5A1BHAF323 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 230DEG SOLDER LUG I roto i te taonga: 2305 pcs</p> <p>RFQ</p>	 <p>AMS22S5A1BHAF318 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 180DEG SOLDER LUG I roto i te taonga: 2228 pcs</p> <p>RFQ</p>
 <p>AMS22S5A1BHAF320 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 200DEG SOLDER LUG I roto i te taonga: 2245 pcs</p> <p>RFQ</p>	 <p>AMS22S5A1BHAF325 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 250DEG SOLDER LUG I roto i te taonga: 1767 pcs</p> <p>RFQ</p>
 <p>AMS22S5A1BHAF327 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 270DEG SOLDER LUG I roto i te taonga: 1734 pcs</p> <p>RFQ</p>	 <p>AMS22S5A1BHAF317 Kaihanga: Bourns, Inc. Whakaahuatanga: SENSOR ROTARY 170DEG SOLDER LUG I roto i te taonga: 1932 pcs</p> <p>RFQ</p>